



Definitions

→ Electrical generation is a process, that convert mechanical energy into electrical energy.

→ In electrical generation is based on the principle, that whenever a flux is cut by a moving conductor, an induced EMF is induced.

→ And the direction is of induced EMF is given by Fleming's Right hand rule.

Principle of Generation:-



(i) When the loop is at position no. 1 the generated EMF is at maximum. The side AB and CD there is not cut any flux. The other sides are parallel to the conductor. When the loop

rotates, the loop is at position no. 2 the coil sides are moving at an angle to the flux and therefore EMF is generated as indicated at point 2 in the figure.

(ii) When the loop is at position no. 3 the coil sides AB and CD are at right angles to the flux lines. So the flux

Cutting is maximum and the emf generated is maximum.

(ii) When the loop is at position no. 4 the generated emf is less because the coil sides are cutting the flux at an angle less than 90° .

(iii) At position no. 5 the flux lines are cut the emf induced is 0V.


(iv) At the position no. 6 the coil sides move under a pole of opposite polarity and hence the direction of generated emf is reversed.

(v) The maximum emf in this direction will be at position no. 7 and 8 when the position is 9.

(vi) This cycle repeats with each revolution.

★ Parts of DC Machine Generation:

* Parts of D.C. Generator



(i) External Cover :-

- It is made up of cast iron.
- It protect the machine from dust and dirt.
- It is provided with radial ventilating ducts to cool the machine.

(ii) Yoke :-

- The shape of the yoke is hollow cylinder.
- It is made up of silicon steel.
- It supports the magnetic poles.
- It provide a return path for magnetic flux.

(iii) Pole :-

- It is fitted with the yoke by means of bolting.
- The pole is laminated in structure to reduce the eddy current loss.
- It is made up of silicon steel.
- It carries the magnetic flux when some current passes through its arm winding.

(vi) Roller shoe :-

- Its function is to compress the effective pole area.
- It makes the field parallel.
- It is also made up of silicon steel.
- It is fitted in the pole by means of rolling.

(vii) Armature :-

- The armature is a cylindrical body.
- Its function is to help the conductor.
- It is also painted to protect it from the weather.

(viii) Insulation :- Insulation is provided to reduce the eddy current loss.

- It is made up of MgO and FeO (insulated material).

(ix) Commutator :-

- It is placed at the other end of the armature.

→ It is made of copper.

- The commutator is made up of different commutator segments.

→ The shape of the commutator is circular.

- It is used to DC in case of generator.


→ Only DC to AC in case of motor.

(x) Brush :-

- It is made up of carbon or copper.

→ Its function is to collect the current.

44 B.S. states that the amp. of the field is given by



Field lines = 2π

It is equal to $2\pi r$ ~~circumference~~ circumference of coil under same pole.

* Definition :-

Winding is a line in which current is flowing i.e. A_1 and A_2 .

* Coil and winding element :-

In the winding A_1 and A_2 along with their end connection is called coil.



Single-bowed winding



Multi-bowed winding

The coil may be single-bowed and multi-bowed.

The sides of the coil is called winding elements.

* Coil pitch or coil span :-


→ Coil pitch is the peripheral distance between 2 sides of a coil measured in terms of no. of commutator slots.

→ If coil pitch is equal to pole pitch then it is called full pitch winding.

winding is called full pitch and end induction is maximum.

* If coil pitch is less than pole pitch then the remaining winding is called short pitch.

* Back pitch (Y_b):



$$Y_b = \frac{P}{2} + 1$$

The distance measured in terms of conductors, which a coil spans in the back end of the armature is called back pitch. It is denoted by Y_b .

* Front pitch: $Y_f = \frac{P}{2} - 1$

The span of armature connections on element spanned by a coil between front side is called front pitch and is denoted by Y_f .

* Resultant pitch:

It is distance between the beginning of one coil and the beginning of next coil is known as Y_r which is connected called as resultant pitch.

* Commutator pitch:

It is the distance measured in commutator between adjacent segments or between the segment

to which both ends of coil is connected, is known as commutator pitch.

Q. Write down the winding table for 2 layer simplex lap winding for 4 pole DC generator having 20 slots.

Given Data

$$\text{Pole } P = 4$$

$$\text{Armature slots } = 20$$

$$\text{Total conductors } = 20 \times 2 = 20 \times 2 = 40$$

$$Y_b = \frac{Z}{P} + 1 = \frac{40}{4} + 1 = 10 + 1 = 11$$

$$Y_f = \frac{Z}{P} - 1 = \frac{40}{4} - 1 = 10 - 1 = 9$$

Back Connection

$$\text{here } Y_b = 11$$

$$1+11=12$$

$$3+11=14$$

$$5+11=16$$

$$7+11=18$$

$$9+11=20$$

$$11+11=22$$

$$13+11=24$$

$$15+11=26$$

$$17+11=28$$

$$19+11=30$$

$$21+11=32$$

$$23+11=34$$

$$25+11=36$$

$$27+11=38$$

$$29+11=40$$

$$31+11=42=40+2$$

$$33+11=44=40+4$$

Front Connection

$$Y_f = 9$$

$$12-9=3$$

$$14-9=5$$

$$16-9=7$$

$$18-9=9$$

$$20-9=11$$

$$22-9=13$$

$$24-9=15$$

$$26-9=17$$

$$28-9=19$$

$$30-9=21$$

$$32-9=23$$

$$34-9=25$$

$$36-9=27$$

$$38-9=29$$

$$40-9=31$$

$$42-9=33$$

$$44-9=35$$

Back Connection

$$25 + 11 = 46 = 40 + 6$$

$$31 + 11 = 42 = 40 + 2$$


$$37 + 11 = 48 = 40 + 8$$

Forward Connection

$$64 - 9 = 55$$


$$46 - 9 = 37$$

$$52 - 9 = 43 = 40 + 3$$




(ii) self excited DC generation :- In self excited DC generation, the induced voltage itself giving supply to the field winding.

Types of DC Generation.



(i) Separately excited DC generation :-



E_g : Generating voltage

R_a : Armature resistance

I_a : Armature current

I_L : Load current

V_t : Terminal voltage

$I_f = I_a$: Field current

R_f : Field resistance


Applying KVL to the loop,

$$E_g - I_a R_a - I_f R_f = 0$$

$$\text{As } I_f = I_a \Rightarrow E_g = I_a R_a + I_a R_f + 0$$

$$I_a = I_L$$

(ii) Self excited 'DC' generator is
 (a) Series Generator :-



R_{se} : Series resistance

R_a : Armature resistance

$$I_a = I_f = I_t$$

For Armature circuit - using field current load eq

V_t : Terminal voltage

Applying KVL in the loop.

$$E_g - I_a R_a - I_a R_{se} - V_t = 0$$

$$\Rightarrow E_g = I_a R_a + I_a R_{se} + V_t \quad (1)$$

$$\Rightarrow E_g = I_a R_a + I_a R_{se} + V_t \quad (1)$$

$$\Rightarrow \boxed{E_g = I_a (R_a + R_{se}) + V_t + I_a L_a \frac{dI_a}{dt}}$$


(b) Shunt generator :-

E_g : Shunt current

R_{sh} : Shunt resistance

$$I_a = I_{sh} + I_L$$

$$I_{sh} = \frac{V_t}{R_{sh}}$$



Applying KVL in the loop.

$$E_g - I_a R_a - V_t = 0$$

$$\Rightarrow \boxed{E_g = V_t + I_a R_a + I_a L_a \frac{dI_a}{dt}}$$

1. Compound Generation (High releasing rate) A.C.

1. Long Short Compound Generation

R_{eq} - Series Resistor

Resistance

R_{eq} - Short field resistance

I_{eq} - Short field current

$$I_{eq} = \frac{V_0}{R_{eq}}$$

$$I_{eq} = \frac{V_0}{R_{eq}}$$

Apply KVL in inner loop

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$

$$V_0 = I_{eq}(R_{eq} + R_{eq} + R_{eq})$$



2. Short Short Compound Generation

$$I_{eq} = \frac{V_0}{R_{eq}}$$

Compound

Apply KVL in divided loop

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$


$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$

$$V_0 = I_{eq}(R_{eq} + R_{eq})$$

Apply KVL in the outer loop

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$

$$V_0 - I_{eq}R_{eq} - I_{eq}R_{eq} - I_{eq}R_{eq} = 0$$



Given Data:

$$I_L = 20 \text{ Amp}$$


$$V_L = 220 \text{ V}$$

$$R_{21} = 0.05 \Omega$$

$$R_{22} = 0.2 \Omega$$

$$R_{23} = 220 \Omega$$

$$V_{20} = 1 \text{ V}$$



$$E_T = I_L R_{23} + I_L R_{22} + V_L + V_{20}$$

$$I_{L1} = \frac{V_L + I_L R_{22}}{R_{21}}$$

$$= \frac{220 + (20 \times 0.2)}{0.05} = \frac{220 + 4}{0.05}$$

$$= \frac{224}{0.05} = 4480 \text{ Amp}$$

$$I_{L2} = I_{L1} - I_L$$

$$= 4480 - 20 = 4460 \text{ Amp}$$

$$V_T = I_{L1} R_{21} - I_{L2} R_{22} + V_{20} + V_{20}$$

$$= (4480 \times 0.05) - (4460 \times 0.2) + 1 + 1$$

$$= 224 - 892 + 2$$

$$= -666 \text{ V}$$

Equation of EMF generated in the generator

Φ = Flux per pole

Z = no. of conductors in the armature

(conductors in each slot)

P = no. of poles

n = no. of revolutions in 1 sec.

E_g = EMF generated

$$E_g = \frac{P \Phi Z n}{60} \text{ (if no. of conductors is in series)}$$

EMF generated per conductor = $\frac{E_g}{Z}$

no. of slots in armature = 24

in one revolution (180°) = 24

No. of revolution in per minute = 1500 rpm
 No. of revolution per second = $\frac{1500}{60}$

Emf generated = $E = \frac{117}{60}$

1 conductor = $\frac{117}{60}$ emf
 10 conductors = $\frac{117}{60} \times 10 = \frac{1170}{60}$ emf
 = 19.5 emf

Emf generated = $E = \frac{117}{60}$ emf

10 conductors = $\frac{1170}{60} = 19.5$ emf

These are the emf generated in 10 conductors

If total no. of conductors = 10, then

The total emf generated = $\frac{1170}{60}$

Now we have 2 types of winding

(i) Lap winding

(ii) Wave winding

For Lap winding, the parallel paths are 2

Emf generated = $\frac{1170}{2} = 585$ emf

For wave winding, the parallel paths are 2

Emf generated = $\frac{1170}{2} = 585$ emf

Q. A 4 pole generator having wave wound armature winding having 11 slots and each slot contains 20 conductors.

Find the speed at which the voltage generated in the machine when it is driven 500 rpm assuming flux per pole is 0.05 Wb.

Prob. Green Book

No. of poles (P) = 4

No. of slots = 5

Conductors in each slot = 20

Total conductors = 100

$T = \frac{100}{P} = 25$

Flux per pole (Wb) = 7 mWb

$$= 7 \times 10^{-3} \text{ Wb}$$

(2011)

No. of field poles (P) = 400 rpm

As the armature winding is wave, $k_p = 1$

So $k_p = 1$

$$\therefore \text{Avg. } \frac{P\Phi Z}{60} = \frac{4 \times 7 \times 10^{-3} \times 100 \times 25}{60 \times 2} = 11.67$$

Q. In a 8 pole DC shunt generator with 475 wave connected armature conductors running at 1500 rpm. Supply a load of 150 A. The terminal voltage is 250 V. The armature resistance is 0.25 Ω and field resistance is 250 Ω . Find the mechanical power developed and efficiency.

Prob. Green Book

P = 8 poles

$R_a = 0.25 \Omega$


$R_f = 250 \Omega$

$R_{sh} = 250 \Omega$

R_{sh}

$k_p = 1$

$Z = 475$



$$I_L = \frac{V_t}{R_L} = \frac{250}{25} = 10 \text{ Amp.}$$

Supply to

$$I_{sh} = \frac{V_t}{R_{sh}} = \frac{250}{250} = 1 \text{ Amp.}$$

$$I_a = I_{an} + I_a = 21 + 1 = 22 \text{ A}$$

$$E_g = I_a R_a + 0.75 P_a V_1$$

$$= (22 \times 0.25) + 0.75 \times 400$$

$$= 305.04 \text{ V}$$

$$= 255.04 \text{ V}$$

Now know,

$$E_g = \frac{P_{out}}{I_a}$$

$$\Rightarrow 255.04 = \frac{3000 \times 75 \times 500}{60 \times 2}$$

$$\Rightarrow Q = \frac{305.04}{2 \times 75 \times 500} \times 60 \times 2$$

$$\Rightarrow Q = 0.75 \text{ mm}^2 \times 10^3 \text{ mm}^2$$

Generated EMF is 255.04 V and flux per pole is 0.75 mm².

Principle of Separation of flux lines

The effect of separation of flux lines with main magnetic flux lines.



(i) effect of

separation of flux lines

Amperian Equations :-


→ The action of circulating flux in a wire, the so called circulating magnetism.

→ The flux arising in a DC machine is that to which poles is called stator flux.

→ The current through the armature conductors creates a magnetic flux called armature flux.


3) Pitch (Armature Winding by 2) :-

→ The conductors placed in a coil that span the angle between the poles are called poles.



4) Pitch (Magnetic Neutral Axis) :-


→ It is the axis drawn perpendicular to the plane of rotation of the machine through the center of the armature.





→ The above figure shows the flux due to the main flux only.

→ The EMF produced during the main flux is Φ_m



→ The above figure shows the flux due to the current flowing to the armature conductor only.

→ The armature conductor left of G.M.M. carry current in inward direction i.e. taken as (-) and those conductor right of the G.M.M. carry current in outward direction i.e. taken as (+).

→ So, the direction of magnetic flux can be found out by ~~some~~ thumb rule.


→ The EMF produced in the armature flux is given by Φ_a



→ The above figure shows the flux due to main pole and the armature conductor.

→ Resultant flux Φ_r is the vector sum of


Of an and DF_A is so, W_{AB} shifted in a angle θ from the main position in W_{AB} axis.



By its action to collect, speed of collection, the number must shift along the W_{AB} due to its break shift. The end DF_A from shift some and so DF_B can be resolved into two components DF_A and DF_B .

→ The component DF_A is known as demagnetizing component and the component DF_B is known as the magnetizing component.

Demagnetizing and Magnetizing component



→ The demagnetizing component is DF_A which acts at right angle to W_{AB} and the DF_B is direct opposite to the main line i.e. the collector lying within the angle $180^\circ - 180^\circ - 2\theta - 2\theta$ which are called demagnetizing component which produces the demagnetizing effect.

→ The collector component lying between the angle $180^\circ - 180^\circ$ collector, which magnetizing effect is so, the collector is called as magnetizing component.

Q. 11, separately excited DC generator has a
 armature circuit resistance of 0.1Ω and total
 brush drop is $2V$ when running at 1000 rpm .
 It delivers a current of 100 amp at 250 V
 to a load of constant resistance.
 If the generator speed drops to 900 rpm with
 field current constant, then find the
 current in the load.

Ans. Given Data-

$$R_a = 0.1 \Omega$$

$$b.p. = 2V$$

$$n_1 = 1000 \text{ rpm}$$

$$I_a = 100 \text{ amp}$$

$$V_t = 250 \text{ V}$$

$$n_2 = 900 \text{ rpm}$$

$$E_g = I_a R_a + V_{b.p.} + E_b$$

$$250 = 100 \times 0.1 + 2 + E_b$$

$$E_b = 250 - 12 = 238 \text{ V}$$

$$E_{g2} = V_t + I_a R_a + E_b \quad \text{--- Eq (1)}$$

$$E_g = I_a R_a$$

$$E_g = \frac{\phi \omega A}{2\pi l}$$

Here, ϕ is constant & ω is constant

Let $K = \frac{\phi \omega A}{2\pi l}$ (constant)

So, $E_g \propto \omega$ or $E_g \propto n$

$$\frac{E_{g1}}{E_{g2}} = \frac{n_1}{n_2}$$

$$\Rightarrow \frac{238}{E_{g2}} = \frac{1000}{900}$$

$$\Rightarrow \frac{238}{E_{g2}} = \frac{1000}{900}$$

$$\Rightarrow E_{g2} = \frac{238 \times 900}{1000} = 214.2 \text{ V}$$

Putting E_{g2} in Eq ①

$$E_{g2} = I_{a2} R_a + V_t + B.D.$$

$$\Rightarrow 183.4 = (I_{a2} \times 0.1) + 250 + 2$$

$$\Rightarrow 183.4 - 252 = 0.1 I_{a2}$$

$$\Rightarrow -68.6 = 0.1 I_{a2}$$

$$\Rightarrow I_{a2} =$$

$$\Rightarrow E_{g2} = I_{a2} R_a + (I_{a2} \times R_L) + B.D. \quad (\because I_{a2} = I_{L2})$$

$$\Rightarrow 183.4 = I_{a2} (R_a + R_L) + 2$$

$$\Rightarrow 183.4 = I_{a2} (0.1 + 2.5) + 2$$

$$\Rightarrow 183.4 = 2.6 I_{a2} + 2$$

$$\Rightarrow 183.4 - 2 = 2.6 I_{a2}$$

$$\Rightarrow I_{a2} = \frac{181.4}{2.6} = 69.76 \text{ Amp}$$

$$\therefore I_{a2} = I_{L2} = 69.769 \text{ Amp}$$

Q. A 4 pole DC shunt generator with a shunt field resistance of 100Ω and Armature resistance of 0.1Ω and has a 378 wave connected conductor in its armature. The flux per pole is 0.02 wb and if the load resistance is 10Ω and it is connected across the armature terminals and the generator driven at 1000 rpm calculate power absorbed by the load.

Given: Given

$$R_1 = 100 \Omega$$

$$R_2 = 100 \Omega$$

$$R_3 = 100 \Omega$$

$$R_4 = 100 \Omega$$

$$R_5 = 100 \Omega$$

$$R_6 = 100 \Omega$$

$$R_7 = 100 \Omega$$

$$I_3 = \frac{100 \text{ mA}}{100 \Omega}$$

$$I_3 = \frac{100 \times 10^{-3} \times 100}{100}$$

$$= \frac{10 \times 10^{-3} \times 100}{100} = 10 \text{ mA}$$

$$I_4 = 10 \text{ mA}$$

$$I_5 = 10 \text{ mA}$$

$$I_6 = 10 \text{ mA}$$

$$I_7 = 10 \text{ mA}$$

$$I_8 = 10 \text{ mA}$$

$$I_9 = 10 \text{ mA}$$

$$I_{10} = 10 \text{ mA}$$

$$I_{11} = 10 \text{ mA}$$

$$I_{12} = 10 \text{ mA}$$

$$I_{13} = 10 \text{ mA}$$

$$I_{14} = 10 \text{ mA}$$

$$I_{15} = 10 \text{ mA}$$

$$I_{16} = 10 \text{ mA}$$

$$I_{17} = 10 \text{ mA}$$

$$I_{18} = 10 \text{ mA}$$

$$I_{19} = 10 \text{ mA}$$

$$I_{20} = 10 \text{ mA}$$

$$I_{21} = 10 \text{ mA}$$

$$I_{22} = 10 \text{ mA}$$

$$I_{23} = 10 \text{ mA}$$

$$I_{24} = 10 \text{ mA}$$

$$I_{25} = 10 \text{ mA}$$

$$I_{26} = 10 \text{ mA}$$

$$I_{27} = 10 \text{ mA}$$

$$I_{28} = 10 \text{ mA}$$

$$I_{29} = 10 \text{ mA}$$



$$I_1 = \frac{V_1}{R_1} = \frac{V_1}{100}$$

$$I_2 = \frac{V_2}{R_2} = \frac{V_2}{100}$$

$$I_3 = \frac{V_3}{R_3} = \frac{V_3}{100}$$

$$= V_1 \left(\frac{10}{100} \right) = \frac{10V_1}{100}$$

Power: P_{max}

$$P_{max} = 2 I_{max} V_1 + 10 \times 10$$

$$= 2 \times 10 \times \left(\frac{10V_1}{100} \right) + 10 \times 10$$

$$= 2 \times 10 \times \left(\frac{10V_1}{100} \right) + 100$$

$$= 2 \times 10 \times \left(\frac{10V_1}{100} \right) + 100$$

$$= \frac{2 \times 10 \times 100}{100} = 200 \text{ mW}$$

$$T_L = \frac{V_L}{R_L} = \frac{227.02}{70} = 3.243$$

$$E_L = 227.02 \times 21.46 = 4871.967 \text{ Volt}$$

~~Designing transformer~~

a) Designing transformer. turn / pole = $\frac{E_L}{2.22 \times 10^8}$

$$\text{turns} = \frac{1}{A}$$

b) Core magnetizing Ampere turn / pole

$$\left[\frac{H}{\text{pole}} = 2.2 \left(\frac{1}{\mu_r} + \frac{B_m}{250} \right) \right] \quad \text{turns} = \frac{1}{A}$$

Q. A 4 pole generator has a core wound around with 720 conductors and it delivers 100 kW at 240 V. The flux density is 2. Calculate the area of the magnetizing core carrying 17/s

Ans: Given Data

$$P = 4$$

$$N = 720$$

$$W = 100 \text{ kW}$$

$$V = 240 \text{ V}$$

Find: Area of the core (cm²)

$$\text{Designing } H/\text{pole} = \frac{900}{250} \times 720$$

$$1 = \frac{c}{A} = \frac{100}{A} = 50$$

$$\frac{A}{100} = \frac{1}{50} \times 720 \times 50$$

$$= 360 \times 50 \text{ cm}^2$$

Demagnetizing AT/pole $= \frac{21}{100} \left(\frac{1}{2.5} - \frac{6}{200} \right) A$

$I = \frac{I_a}{2} = \frac{100}{2} = 50$

AT/pole $= 782.50 \left(\frac{1}{2.5} - \frac{6}{200} \right)$
 $= 3710.25 \text{ AT/pole}$

Q.5. A 8 pole lap connected DC shunt generator delivers an output current of 240 amp at 500V. The armature has 1402 conductors and 150 commutator segments. If the brushes are given a lead of 4 segments from the long neutral axis find the demagnetizing and cross magnetizing AT/pole.

Given Data

$P = 8$

$A = 2 = 8$

$Z = 1402$

$V_t = 500 \text{ V}$

$\alpha = 140^\circ$

1st commutator segment = 150

So, the commutator = 300

1 Commutator = $\frac{300}{150} = 2.25$

Brushes are lead for 4 commutator segments.

So, angle $(\theta_a) = 2.25 \times 90^\circ$

θ_a is not given so, $\theta_a = 0$

So, $T_a = I_a = 240 \text{ amp}$

Demagnetizing AT/pole $= \frac{Z_p}{200} \times 2.1$


$I = \frac{I_a}{2} = \frac{240}{2} = 120$



$$K_{T/pole} = \frac{1}{2} \times 1408 \times 30 = \frac{1408 \times 30}{40} = 1056$$

$$\begin{aligned} \text{Cross magnetizing } K_{T/pole} &= \frac{2}{3} \times 2I \left(\frac{1}{2\phi} - \frac{\theta_m}{2\phi} \right) \\ &= 1408 \times 20 \left(\frac{1}{2\phi} - \frac{9}{36} \right) \\ &= 1408 \times 30 \left(\frac{1}{16} - \frac{1}{4} \right) \\ &= -1544.44 = 1544 \end{aligned}$$


Compensating winding



→ The demagnetizing effect of armature reaction can be neutralized by compensating winding.

→ A compensating winding is a auxiliary winding embedded in slots in pole shoe as shown in the figure. It is connected in series with the armature winding in manner so that the direction current through the compensating winding in any pole face will be opposite to the direction of current through the adjacent armature conductors.


★ Concentration



The portion of which the commutator current passes through the brush is

The reversal of current in a coil as the coil passes through the brush area is called commutation.

→ In figure (i) the brush is in contact with segment 3 & 4. The coil current flows through the brush to segments 3 & 4 and to the load.




→ If the brush is pulled to the right with a force $\frac{1}{2}$ contact with segment 2 and $\frac{1}{2}$ contact with segment 3. Again the current carried through the brush is split. The interp through segment 2 and interp through the segment 3.



→ The direct current carries the current when the brush is in contact with segment 2 and $\frac{1}{2}$

Contact with segment 2 and the total current will flow through the brush.

i.e. going through segment 2 and going through segment and the current through coil 1 is 2A.




→ The above figure shows the instant when the brush is in contact with segment 2 and the current flow through the brush for the 2A through segment 2 and through segment 3 and the current in the coil is 1A and the current direction is




→ The above figure shows the instant when the brush is in contact with segment 3 and the current flow through the brush for the 1A from coil 1 and coil 2.

Improvement in Commutation :-



If the current changes at a uniform rate (i.e. BC is a straight line) then it is called ideal commutation. Under such condition no sparking will take place between brush and commutation.



The ideal commutation can not be attained in practice because the armature coil has some inductance when the current changes in the coil so, a generated voltage is induced in opposite direction to the current flowing through it.

This back EMF voltage opposes the change of current so the commutation occurs more slowly than ideal commutation.

The Curve BC represents the ^{Current} ^{direction} ^{next} ^{current} direction.

DC = 8 Amp. i.e. flowing from the commutator segment to brush when the brush has no contact with the commutator segment.

So, we need to improve the commutation process.

There are 2 methods to improve the commutation.

(i) Resistance Commutation

(ii) EMF Commutation

(i) Resistance Commutation :-

→ If the contact resistance between the brush and commutator is made large, the current would divide in the inverse ratio of the contact resistance and this improves the commutation and it is achieved by Carbon brush.

(ii) It is called Resistance Commutation.

(i) EMF Commutation :-

In this method an arrangement is made to neutralise the reactance voltage by producing a reversing voltage in the coil undergoing commutation.

The reversing voltage is the opposite to the reactance voltage.

and it is achieved by 2 ways

(i) By brush shifting

(ii) By using Interpole

Q. A separately excited DC generator running at 1200 rpm supply a current of 200A at 125V to circuit of constant resistance. What will be the current when the speed is drop to 1000 rpm and the field current reduced to 80%. Armature resistance is 0.05Ω and total br P.D. is 2V.

Given Data

$N_1 = 1200 \text{ rpm}$

$R_a = 0.05\Omega$

$I_a = 200A$

$V_t = 125V$

$N_2 = 1000 \text{ rpm}$

We know,

Equation

$$E_g = \frac{\Phi Z N}{60A}$$

Equation

$$\Phi_2 = 80\% \text{ of } \Phi_1 = \frac{80}{100} \times \Phi_1$$

$$\frac{E_{g1}}{E_{g2}} = \frac{\Phi_1 N_1}{\Phi_2 N_2}$$

$$\Rightarrow \frac{125}{E_{g2}} = \frac{200}{1000} \times 0.8 \times \frac{1200}{1000}$$

$\Rightarrow E_{g2}$

$$R_a = \frac{V_t}{I_a} = \frac{125}{200} = 0.625\Omega$$

$$E_g = I_a R_a + V_t + P.D.$$

$$= (200 \times 0.05) + 125 + 2 = 129V$$

E_g d.o.m

$$\frac{E_{g1}}{E_{g2}} = \frac{\Phi_1 N_1}{\Phi_2 N_2}$$

$$\Rightarrow \frac{129}{E_{g2}} = \frac{\Phi_1 \times 1200}{0.8 \times \Phi_1 \times 1000} \Rightarrow E_{g2} = \frac{129 \times 0.8 \times 1200}{1000}$$

$$b) \quad E_{Th} = \frac{V_2}{\frac{R_1 R_2}{R_1 + R_2}} = \frac{1.5}{\frac{10 \times 10}{10 + 10}} = 1.5 \text{ V}$$

$$E_{Th} = V_{Th} + I_{Th} R_{Th} \quad \text{a.p.}$$

$$1.5 = V_{Th} + 10 \times 10^{-3} R_{Th} + 0.1$$

$$1.4 = V_{Th} + 0.1 R_{Th} \quad \text{a.p.}$$

$$V_{Th} = 1.4 - 0.1 R_{Th} \quad \text{a.p.}$$

$$1.4 = 1.4 - 0.1 R_{Th} + 0.1 R_{Th} + 0.1$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$


$$1.4 = 1.4 + 0.1 R_{Th}$$

$$1.4 = 1.4 + 0.1 R_{Th}$$


$$1.4 = 1.4 + 0.1 R_{Th}$$

Internal Characteristics of a Synchronous Generator


Internal characteristics of a synchronous generator are shown below.




Internal Characteristics of a Synchronous Generator



External Characteristics of a Synchronous Generator



Voltage build-up in self-excited DC generator




Voltage build-up phenomenon occurs in a self-excited generator. Due to the residual magnetism, initially the voltage generated is small. Due to this voltage, the generation is on. Due to this voltage, the

field current increased to a_b . Due to increase of field current the voltage is again increased to b due to the increase of voltage the field current is again increased to a_d . Thus the intersection of the curves if we increase the field current then the voltage will come due to the saturation of the field current.

By the above process voltage build up takes place very is with continuous till this intersection point of R_b with the open circuit characteristic.

* Critical Resistance :-




Resistance below which there is no voltage build up takes place and above which there is no voltage build up.


* Characteristics of the motor :-

1. No load speed characteristics


2. ω vs I_a



(b) Internal Characteristics of a self-excited generator
 $E_g \propto I_a$



(c) External Characteristics of




Any decrease of load resistance brought in
 just instead of increasing the load
 current decreases the load current and
 external characteristics curve goes back,
 as shown in the figure.




* Characteristics of self excited DC series generator.

(i) No load characteristics :-




However in series generator the field winding is separately excited for experimental purpose.

(ii) Internal characteristics :-




(iii) External characteristics :-



$$E_g = I_a R_a = V_t$$

* Characteristics of self excited DC compound generator:-

External characteristics characteristics:-



Curve-1 (Over excited):-

If the series winding turns are adjusted that with increase in load current the terminal voltage increases then it is called over excited compound generator.

Curve-2 (Flat excited):-

If the series winding turns are so adjusted that with increase in load current the voltage remains constant then it is called flat excited DC compound generator.

Curve-3 (Under excited):-

If the series winding turns are so adjusted that with increase in load current the terminal voltage decreases then it is called under excited DC compound generator.

Losses due to conduction :-

i) Conduction loss :-
by window loss

ii) Conduction loss :-
by pipe loss

iii) Conduction loss :-
by door loss (amount of heat loss)

iv) Conduction loss :-
by wall loss (amount of heat loss)

v) Conduction loss :-
by roof loss (amount of heat loss)

vi) Conduction loss :-
by floor loss (amount of heat loss)

vii) Conduction loss :-
by chimney loss (amount of heat loss)

viii) Conduction loss :-
by boiler loss (amount of heat loss)

ix) Conduction loss :-
by engine loss (amount of heat loss)

$$P_0 = \mu_0 k^2 B_m^2 V \omega^2$$

where, ω = frequency of rotation

B_m = magnetic flux density

V = volume of the body

k = thickness of the layer

μ_0 = permeability constant

Hysteresis Loss

In a cyclic magnetic process, the magnetic flux density B and the current i varies in a cyclic manner. The magnetic flux density B is plotted against the current i and the area under the curve represents the hysteresis loss.


The area under the curve is divided into two parts, one for the positive half cycle and one for the negative half cycle.

The area under the curve is divided into two parts, one for the positive half cycle and one for the negative half cycle.

The area under the curve is divided into two parts, one for the positive half cycle and one for the negative half cycle.

The area under the curve is divided into two parts, one for the positive half cycle and one for the negative half cycle.

The area under the curve is divided into two parts, one for the positive half cycle and one for the negative half cycle.



$$P_h = \frac{1}{T} \oint B \cdot H \, dV$$

where, P_h = hysteresis loss

T = time period of the cycle

$\oint$ = closed path integral

B = magnetic flux density

H = magnetic field strength

dV = volume element

V = volume

$$P_h = \frac{1}{T} \oint B \cdot H \, dV$$

where, P_h = hysteresis loss

T = time period of the cycle

$\oint$ = closed path integral

B = magnetic flux density

H = magnetic field strength

dV = volume element

V = volume

Hamiltonian $H = \frac{p^2}{2m} + V(x)$

Energy $E = \frac{p^2}{2m} + V(x)$
 Total Energy = Kinetic Energy + Potential Energy

Total Energy = Constant Energy + variable energy
 $= E_0 + \text{variable term (like } \hbar \omega)$

$H = \frac{p^2}{2m} + V(x)$ $\rightarrow$ free term + interaction field (like $\hbar \omega$)

Distance $(r) = \frac{v_p}{\omega} = \frac{v_p}{\omega_p + \text{frequency}}$

$P_{in} = P_{out} + \text{loss}$

if $\omega_p > \omega$ $\rightarrow$ $\frac{P_{out}}{P_{in}}$ $\rightarrow$ $\frac{1}{1 + \frac{\omega_p^2}{\omega^2}}$

$\frac{P_{out}}{P_{in}} = \frac{1}{1 + \frac{\omega_p^2}{\omega^2}}$

if $\omega_p < \omega$ $\rightarrow$ $\frac{P_{out}}{P_{in}} = \frac{1}{1 - \frac{\omega_p^2}{\omega^2}}$ (if $\omega_p < \omega$)

if $\omega_p = \omega$ $\rightarrow$ $\frac{P_{out}}{P_{in}} = \frac{1}{1 - \frac{\omega_p^2}{\omega^2}}$ (if $\omega_p = \omega$)

Correlation time $\rightarrow$ maximum duration $\frac{1}{\omega_p - \omega}$

if $\omega_p = \omega$ $\rightarrow$ $\frac{1}{1 - \frac{\omega_p^2}{\omega^2}}$ (Correlation time $\rightarrow$ $\frac{1}{\omega_p - \omega}$)

$\frac{1}{1 - \frac{\omega_p^2}{\omega^2}} = \frac{1}{1 - \frac{\omega_p^2}{\omega^2}}$

$$\frac{d}{dt} (V_t I_a + W_c + I_a^2 R) = 0$$

$$\Rightarrow \frac{d}{dt} (V_t I_a) + \frac{dW_c}{dt}$$

dividing $V_t I_a$ in both numerator and denominator

$$\frac{\frac{V_t I_a}{V_t I_a}}{\frac{V_t I_a + W_c + I_a^2 R}{V_t I_a}} = \frac{1}{1 + \frac{W_c}{V_t I_a} + \frac{I_a R}{V_t}}$$

$$\frac{1}{1 + \frac{W_c}{V_t I_a} + \frac{I_a R}{V_t}}$$

$$\frac{d}{dt} \left[\frac{1}{1 + \frac{W_c}{V_t I_a} + \frac{I_a R}{V_t}} \right] = 0 \quad \text{or we can take } \frac{d}{dt} \left(\frac{1}{1 + \frac{W_c}{V_t I_a} + \frac{I_a R}{V_t}} \right)$$

$$\Rightarrow 0 + \frac{W_c}{V_t} (-I_a^{-2}) + \frac{R}{V_t} = 0 \quad \left(\because \frac{d}{dt} \left(\frac{1}{I_a} \right) = -I_a^{-2} \right)$$

$$\Rightarrow \frac{R}{V_t} = \frac{W_c}{V_t I_a^2}$$

$$\Rightarrow R = \frac{W_c}{I_a^2}$$

$$\Rightarrow \boxed{W_c = I_a^2 R}$$

$$\Rightarrow \text{var. Constant loss} = \text{variable loss}$$

When variable loss equal to constant loss

the efficiency will be maximum.

Power stages of DC Machine :-



Efficiency:-

(i) Electrical efficiency:-

$$\eta_e = \frac{P_o}{P_g} \left(\frac{\text{electrical gp}}{\text{electrical ip}} = \eta_e \right)$$

(ii) Mechanical efficiency:-

$$\eta_m = \frac{P_o}{P_g} \left(\frac{\text{electrical gp}}{\text{mechanical ip}} = \eta_m \right)$$

(iii) Overall Efficiency:-

$$\eta_o = \frac{P_o}{P_g} \left(\frac{\text{electrical gp}}{\text{mechanical ip}} = \eta_o \right)$$

Q. A short generator delivers 195 Amp. at terminal voltage 250V. The armature resistance and shunt resistance 0.02 Ω and 50 Ω respectively. The iron and friction loss is 950 watt. Find

- EMF generated
- Copper loss
- Output & prime mover
- Mechanical, electrical and overall efficiency.

Ans Given Data

$$I_L = 195 \text{ amp}$$


$$V_L = 250 \text{ V}$$

$$R_a = 0.02 \Omega$$

$$R_{sh} = 50 \Omega$$

Iron & friction

$$\text{loss} = 950 \text{ watt}$$



$$I_{sh} = \frac{V_L}{R_{sh}} = \frac{250}{50} = 5 \text{ Amp}$$

$$I_a = I_L + I_{sh} = 195 + 5 = 200 \text{ amp}$$

$$(i) E_g = I_a R_a + V_L + A.P.$$

$$= (200 \times 0.02) + 250 + 0$$

$$= 4 + 250 = 254 \text{ V}$$

(b) Copper loss $P_{Cu} = 100 \times 0.02 = 200 \text{ watt}$

$$I_a^2 R_a = 200 \times 0.02 = 200 \text{ watt}$$

$$I_a^2 R_{sc} = 200 \times 5 = 1000 \text{ watt}$$

$$I_a^2 R_a + I_a^2 R_{sc} = 200 + 1000 = 1200 \text{ watt}$$



$$P_1 = 1200 \text{ W} = P_2 = 1000 \text{ W}$$

$$\Rightarrow P_1 = P_2 = 1000 \text{ W}$$

$$\text{Ans } P_1 = P_2 = 1000 \text{ W}$$

(c) Output of prime mover

$$P_1 = P_2 = 1000 \text{ W}$$

$$= 1000 \times 1000 = 1000000 \text{ W}$$

$$= 1000000 \text{ W} = 1000 \text{ kW}$$

$$\text{Circuit not shown. } P_1 = 1000 \text{ W} = 1000 \times 1000 = 1000000 \text{ W}$$

(d) Mechanical efficiency

$$\eta = \frac{P_2}{P_1} = \frac{1000000}{1000000} = 1.0 = 100\%$$

(e) electrical efficiency

$$\eta_e = \frac{P_2}{P_1} = \frac{1000000}{1000000} = 1.0 = 100\%$$

(f) overall efficiency

$$\eta_o = \frac{P_2}{P_1} = \frac{1000000}{1000000} = 1.0 = 100\%$$

Q. A shunt generator has a full load current of 196 Amp. at 220V. The stray losses are 720 watt, and shunt field resistance is 55Ω . If it has a full load efficiency of 88%. Find the armature resistance. Also find the load current corresponding to maximum efficiency.

Given data

$I_L = 196 \text{ Amp.}$

$V_t = 220 \text{ V}$

Stray losses (Excitation loss)

$$= 720 \text{ watt} \quad \frac{100}{100} = 100\%$$

$R_{sh} = 55\Omega$

Full load efficiency (overall efficiency)

$$\frac{E}{A} = \eta_o = 88\%$$



$$I_{sh} = \frac{V_t}{R_{sh}} = \frac{220}{55} = 4 \text{ Amp.}$$

$$I_a = I_L + I_{sh} = 196 + 4 = 200 \text{ Amp.}$$

$$E_g = I_a R_a + V_t + A.D.$$

$$\frac{E}{A} = 88\%$$

$$\frac{V_t I_L}{A} = \frac{88}{100}$$

$$\frac{220 \times 196}{A} = \frac{88}{100}$$

$$\Rightarrow \frac{220 \times 196 \times 100}{88} = A$$

$$\Rightarrow A = 49000 \text{ watt}$$

Power at output of inductor is $P_{out} = 1000 \text{ W}$
 $P_{in} = P_{out} + P_{loss} = 1000 + 100 = 1100 \text{ W}$

$P_{in} = I_{in}^2 R_{in} = 1100 \text{ W}$ $R_{in} = 10 \Omega$

$I_{in} = \sqrt{\frac{P_{in}}{R_{in}}} = \sqrt{\frac{1100}{10}} = 10.488 \text{ A}$

$P_{out} = I_{out}^2 R_{out} = 1000 \text{ W}$ $R_{out} = 10 \Omega$

$I_{out} = \sqrt{\frac{P_{out}}{R_{out}}} = \sqrt{\frac{1000}{10}} = 10 \text{ A}$


$P_{in} = I_{in}^2 R_{in} = 1100 \text{ W}$

$P_{out} = I_{out}^2 R_{out} = 1000 \text{ W}$

$P_{in} = I_{in}^2 R_{in} = 1100 \text{ W}$

$P_{out} = I_{out}^2 R_{out} = 1000 \text{ W}$

* The following are the requirements of a good generator:



1. It should be able to supply power to the load.

2. It should be able to supply power to the load.

3. It should be able to supply power to the load.

4. It should be able to supply power to the load.

5. It should be able to supply power to the load.

6. It should be able to supply power to the load.

7. It should be able to supply power to the load.

8. It should be able to supply power to the load.

9. It should be able to supply power to the load.

10. It should be able to supply power to the load.

11. It should be able to supply power to the load.

12. It should be able to supply power to the load.

→ The armature of generator is excited by prime mover.

→ The excitation of generator is changed by the voltmeter. When the voltmeter reads to zero value, then it means that the terminal voltage is same as no-load voltage. After that the switch is closed so, the generator is parallel to the system. Under this condition, the generator is not taking the load because the induced EMF is same as the terminal voltage. So, the generator is called floating condition.

When there is a load requirement the induced EMF of generator should be greater than the induced voltage as system voltage.

Q. A short generator with one pole.

Resistance of 20 Ω and field resistance of 20 Ω respectively. To supply a load of 2000 W at the end with terminal voltage of 200 V. Calculate the induced voltage and power at each machine.

Ans. Given Data:

$$R_a = 20 \Omega$$

$$R_f = 20 \Omega$$

$$P = 2000 \text{ W}$$

$$V_t = 200 \text{ V}$$

$$E_g = ?$$


$$E_f = ?$$

$$V = ?$$

$$I_a = ?$$

$$I_f = ?$$

$$P_g = ?$$



$$E_{g1} = I_{a1} R_a + V + I_{a1} D$$

$$E_{g1} = 230 R_a + V + I_{a1} D$$

$$\Rightarrow 210 = I_{a1} (230 + 0.01 + 0.01 + 0.01)$$

$$\Rightarrow \frac{210}{0.03} = I_{a1} \times 400 \Rightarrow I_{a1} = \frac{210}{400} = 0.525 \text{ A} \quad \text{--- Eq (1)}$$

$$E_{g2} = I_{a2} R_a + V + I_{a2} D$$

$$\Rightarrow 210 = I_{a2} (230 + 0.01 + 0.01 + 0.01)$$

$$\Rightarrow \frac{210}{0.03} = I_{a2} \times 400 \Rightarrow I_{a2} = \frac{210}{400} = 0.525 \text{ A} \quad \text{--- Eq (2)}$$



As we know
Eqn $I_{a1} = I_{a1} + I_{a2}$

$$I_{a1} = I_{a1} + I_{a2}$$

$$I_{a1} = I_{a1} + \frac{V}{R_a}$$

and

$$I_{a1} = I_{a1} + \frac{V}{R_a}$$

$$I_{a1} = I_{a1} + \frac{V}{R_a}$$

$$I_{a1} = I_{a1} + \frac{V}{R_a}$$

putting the value of I_{a1} in Eq (1)

$$210 = 0.03 (I_{a1} + \frac{V}{R_a})$$

$$\Rightarrow 210 = 0.03 I_{a1} + 0.03 \frac{V}{R_a}$$

$$\Rightarrow 210 = 0.03 I_{a1} + \frac{0.03 \times 230}{0.01}$$

$$\Rightarrow 210 = 0.03 I_{a1} + 6.9$$

$$\Rightarrow 210 = 0.03 I_{a1} + \frac{230 \times 0.03}{0.01}$$

$$\Rightarrow 210 = 0.03 I_{a1} + \frac{230 \times 0.03}{0.01} \Rightarrow I_{a1} = \frac{210 - 6.9}{0.03} = 6700 \text{ A} \quad \text{--- Eq (3)}$$

$$\Rightarrow 210 \times 0.03 + 230 \times 0.03 = 0.03 \times 6700 \Rightarrow I_{a1} = 6700 \text{ A} \quad \text{--- Eq (4)}$$

putting I_{L2} in Eq (ii)

$$220 - \left(I_{L2} + \frac{V}{20} \right) 0.01 = V$$

$$\Rightarrow 220 - 0.01 I_{L2} - \frac{V}{20} \times 0.01 = V$$

$$\Rightarrow 220 - 0.01 I_{L2} = V + \frac{V}{20} \times 0.01$$

$$\Rightarrow 220 - 0.01 I_{L2} = V + \frac{V}{2000}$$

$$\Rightarrow 220 - 0.01 I_{L2} = \frac{2001V}{2000}$$

$$\Rightarrow \frac{2001V}{2000} + 0.01 I_{L2} = 220$$

$$\Rightarrow 2001V + 20 I_{L2} = 220 \times 2000$$

$$\Rightarrow 2001V + 20 I_{L2} = 440000 \quad \text{Eq (iii)}$$

~~Subtracting~~

$$\text{Eq (iii)} - \text{Eq (i)}$$

$$2001V + 20 I_{L1} = 420000$$

$$2001V + 20 I_{L2} = 440000$$

$$20 I_{L1} - 20 I_{L2} = 20000$$

$$\Rightarrow I_{L1} - I_{L2} = \frac{20000}{20} = 1000 \quad \text{Eq (iv)}$$

$$I_{L1} + I_{L2} = 4000 \quad \text{Eq (v)}$$

$$I_{L1} + I_{L2} = 4000$$

$$I_{L1} - I_{L2} = 1000$$

$$2 I_{L1} = 5000 \Rightarrow 1000 \times \frac{5000}{2} = 1500 \text{ Amp}$$

$$I_{L1} + I_{L2} = 4000$$

$$\Rightarrow 1500 + I_{L2} = 4000$$

$$\Rightarrow I_{L2} = 4000 - 1500 = 2500 \text{ Amp}$$

Ans

to $I_{L2} = \frac{V}{R_{L2}}$ putting I_{L2} in Eq (iii)

$$\Rightarrow 420000 = 20I_{L2} + 200V$$

$$\Rightarrow 420000 - 20I_{L2} = 200V$$

$$\Rightarrow 420000 - 20 \times 1500 = 200V$$

$$\Rightarrow 420000 - 30000 = 200V$$

$$\Rightarrow V = \frac{390000}{200} = 1950 \text{ V}$$

$$P_{L1} = V \times I_{L1} = 1950 \times 1500 = 292500 \text{ watt}$$

$$P_{L2} = V \times I_{L2} = 1950 \times 7500 = 1462500 \text{ watt}$$


$$P_{L2} = V \times I_{L2} = 1950 \times 7500 = 1462500 \text{ watt}$$



DC Motor


Working Principle of DC Motor:

The machine which convert electrical energy to mechanical energy is called DC motor.



When some voltage is applied to the terminals of the motor, the current in the field winding is $I_m = \frac{V}{R_m}$. Due to this field current the magnetic pole will excite and they will behave as magnet. Due to this terminal voltage & some current will flow in the armature winding. This is the case when a current carrying conductor placed inside the magnetic field.

According to the basic principle of Electromagnetism when a current carrying conductor placed in the magnetic field it experiences a torque and the direction of torque is given by Fleming's Right hand rule.



Types of Motors :-

Types of Motors :-

Separately
excited

Self
excited

Series

Shunt
Motor

Compound

Short
Shunt

Long
Shunt

(i) Separately excited Motor :-




Apply KVL in the loop :-

$$V_t - I_a R_a - E_b = 0$$

$$\Rightarrow V_t = E_b + I_a R_a$$

$$I_a = \frac{V_t - E_b}{R_a}$$

(ii) Self excited shunt motor :-



Apply KVL

Apply KVL in the loop-

$$V_1 = I_1 R_{sc} + I_1 R_a + E_b + B \cdot D$$


$$\Rightarrow V_1 = I_1 R_{sc} + I_1 R_a + E_b + B \cdot D$$

$$I_a = I_{sc}$$

$$\Rightarrow V_1 = I_a R_{sc} + I_a R_a + E_b + B \cdot D$$

$$= I_a (R_{sc} + R_a) + E_b + B \cdot D$$

(ii) Self-excited shunt motor




$$I_{sc} = \frac{V_1}{R_{sc}}$$

Apply KVL in the loop

$$V_1 = I_a R_{sc} + I_a R_a + E_b + B \cdot D$$

$$\Rightarrow \frac{V_1}{R_{sc} + R_a + R_f} = \frac{E_b + B \cdot D}{R_{sc} + R_a + R_f}$$

(iii) Long shunt compound motor



$$I_{sc} = \frac{V_1}{R_{sc}}$$

Apply KVL in the loop

$$V_1 = I_a R_{sc} + I_a R_a + E_b + B \cdot D$$

$$\Rightarrow V_1 = I_a R_{sc} + I_a R_a + E_b + B \cdot D$$

$$3) \boxed{V_t = I_a (R_a + R_{a'}) + E_b + R_a I_a}$$

$$I_a = 5.11 \text{ A}$$

(ii) Shunt Shunt compensated motor:



$$I_{a'} = \frac{V_t + E_b R_a}{R_a}$$

Apply KVL in loop

$$V_t = I_a R_a + I_a R_{a'} + E_b + R_a I_a$$

$$3) \boxed{V_t = I_a R_a + I_a R_{a'} + E_b + R_a I_a}$$

$$\boxed{I_a = I_t - I_{a'}}$$

Significance of back EMF (E_b):

Since the generated emf is opposite to motor appears after it, the motor emf.

Compensates E_b , it is called back emf (E_b)

$$\text{In a motor } E_b = \frac{V_t - I_a R_a}{k \phi}$$

$$\text{In a motor } E_b = \frac{V_t - I_a R_a}{k \phi}$$

At the time of starting $E_b = 0$

$$I_a = \frac{V_t}{R_a} \text{ Since } R_a \text{ is very low value}$$

Voltage has a high value and resistance

Resistance has a small value is a

large amount of current is drawn with

flow through the armature winding.

which will heat the armature winding.

Condition for Maximum Efficiency is

$$E_b = V_s \text{ when } \omega C = 1/\omega L$$

$$\Rightarrow C_b L = V_s I_a / \omega^2 R_a \text{ when } \omega = 1/\sqrt{L C_b}$$

$$\frac{d}{dL} (C_b L) = 0 \quad \frac{d}{dL} (V_s I_a - I_a^2 R_a) = 0$$

$$\Rightarrow V_s = 2 I_a R_a$$

$$\Rightarrow V_s = 2 I_a R_a$$

$$\Rightarrow I_a R_a = \frac{V_s}{2} \text{ --- } \omega C = 1/\omega L$$

Putting $I_a R_a$ in eq (1)

$$C_b L = V_s / \omega^2 R_a$$

$$\Rightarrow \boxed{I_a R_a = \frac{V_s}{2}} \text{ Condition for maximum efficiency}$$

Hence when the back EMF is half of the applied voltage maximum power will be delivered.

Q. A 440 V DC motor has a armature resistance of 2 ohm and the field winding is connected in parallel with the armature. The motor is supplied with 440 V and runs at 1500 rpm.

Find Armature current.

$$I_a = 440 / 2 = 220 \text{ A}$$

$$R_a = 2 \text{ ohm}$$

$$R_f = 2 \text{ ohm}$$


$$P_{in} = 440 \times 220 = 96800 \text{ W}$$

$$E_b = V_s - I_a R_a = 440 - 220 \times 2 = 0 \text{ V}$$

$$\Rightarrow \text{Motor is in stall condition}$$

$$\Rightarrow \text{Motor is in stall condition}$$

$$\eta = \frac{P_{out}}{P_{in}}$$



$$\Rightarrow 0.85 = \frac{1.44 \times 10^3 \times 0.2}{P_{LP}}$$

$$\Rightarrow P_{LP} = \frac{1.44 \times 10^3 \times 0.2}{0.85} = 337.647 \text{ W}$$

$$P_{LP} = V_L \times I_L =$$

$$\Rightarrow 337.647 = 240 \times I_L$$

$$\Rightarrow I_L = \frac{337.647}{240} = 1.407 \text{ Amp.}$$

$$I_{LM} = I_{L1} + I_{L2}$$

$$I_{LM} \times \frac{V_L}{R_{LM}} = \frac{1440}{230} = 6.26 \text{ Amp.}$$

$$I_L = I_{L1} + I_{L2} \times 10$$

$$\Rightarrow I_{L1} = I_L - I_{L2} = 1.407 - 0.12 = 1.2874$$

Apply KVL in the loop

$$V_L = I_{L1} R_L + I_{L2} R_L$$

$$240 = 1.2874 \times R_L + 0.12 \times R_L$$

$$\Rightarrow R_L = \frac{240 - 0.12 \times R_L}{1.2874 + 0.12} = 145.807 \Omega$$

Q2. A 220V 50W resistance has a maximum resistance of 0.5 Ω . The full load current is 20A. Find the induced EMF when the machine acts as generator.

Given Data:

$$V_L = 220 \text{ V}$$


$$R_L = 0.5 \Omega$$

$$I_L = 20 \text{ A}$$

* The generated EMF

$$E_g = V_L + I_L R_L + I_a R_a$$

$$= 220 + (20 \times 0.5) = 230 \text{ V}$$



Ex 10, Mysen 2012

$$V_1 = I_1 R_{A1} + E_{B1} R_{B1}$$


$$\Delta V_1 = I_1 R_{A1} + E_{B1} R_{B1} = \frac{100 \times 10^{-3} \times 10}{100} = 10 \text{ mV}$$

$$\Delta E_B = 520 - (50 \times 10^{-3})$$

$$= 520 - 50 = 470 \text{ mV}$$

$$I_1 = 10 \text{ mA}, E_B = 520 \text{ mV}$$

3-point measurement



Studs. It has a soft iron piece which is pulled by the no volt coil and the handle returns to its position as long as the current flows through the no. voltage coil.

(ii) Spring :- It is wound on the handle of the starter. The function of spring is to pull the handle to OFF position when the supply fails. Tension of the spring is such that when the handle is at the OFF position immediately after the no volt coil is demagnetised, the handle returns to its original position.

It is an electromagnet which is connected in series with the starter coil. The coil is magnetised by the current flowing in the starter coil. As the starter handle is in the ON position, the current of supply falls. The no volt coil is demagnetised and the handle returns back to OFF position when the tension of spring thereby disengages the motor from the main.

(iii) Over load coil :- It is also an electromagnet which is connected in the line and the handle. It consists of a fixed number of thick wires.

the current flowing in the armature. If due to any reason (fault or over load) the load current is increased, the no volt coil terminals are short circuited by the over load coil lever. The no volt coil terminals are shorted & is demagnetised and then to release the handle which return to OFF position automatically by the spring action. Thus, the motor stops. So it is called over load & release coil.

Function of a D.C. three point starter with no volt and over load release.

The starter is a device which is used for the safety of D.C. motor. A three point starter is used for starting the D.C. motor, on the starter face plate there are three terminals which are marked as L, A, F.

The positive wire (line) is connected to the L terminal. The A and F terminals are connected to armature and field respectively. This starter also consists of a variable resistance and two coils called the no volt coil (N.V.C) and Over load coil (O.L.C) as shown in the figure. The N.V.C is wound by many turns of thin wire and is connected in series with the shunt field.

The O.L.C consists of few turns of thick wire and is connected in series with the line and handle. The handle of the starter is moved from OFF position before starting. When the handle is moved to stud number 1 the whole

Resistance is in series with the windings of the
of the motor goes up, the handle of induction
from start position (C) and position to the
the motor should attain its normal speed, and
complete resistance is brought in, the magnetic
induction. The motor is magnetized by current
flowing in the short field, the handle of
the starter is held in the on position. At
any of time the supply goes on or off, the
is de-energized and it maintains the handle
and goes back to the off position by the
spring force. In case of heavy loads, when
starting, the motor will take high
current, the motor is magnetized and
will start the motor through about 100% of
the rated current of the motor. The motor will
be magnetized and it will maintain the
induction, and it will be in off position
by the spring force. The motor is
starting of the motor from point A to point B
The motor is started in point A, the motor
on a normal speed. It has the resistance
removed as it starts. A motor is started in
the starter, the motor will be energized and
start the motor through a protection device
unlike the three point starter, in which it is
in series with the field. The construction is
similar to that of a three point starter. This

starter is used at places where much speed
 regulation is required. For maximum reduction
 of speed in high resistance is connected in
 series with the control field winding.
 If this resistance is used in three point starter,
 it will reduce the short field starting current.
 It means the current passing through the M.C.
 is also decreased. Therefore, the no volt coil
 will not be able to produce sufficient magnetic
 strength and therefore, release the handle to the
 OFF position. This problem has been rectified in
 three point starter so that no-volt coil does not have
 a strong magnet.

Characteristics of D.C. Motor - $\frac{T}{\omega} \propto \phi$

Speed, ω , vs. Torque, T

1. Torque vs. speed curve

Equation and the ϕ

for speed

$E_b = k \omega$

in series motor

$I_f = I_a$

$\phi \propto I_a$

$T_a = P_{mech}$

$\omega T_a = 1000 \text{ p.w}$

$\omega T_a = \frac{2\pi}{60} I_a \phi \omega$

$\Rightarrow \frac{T_a}{I_a} = \frac{2\pi \phi}{60}$

$\phi = \frac{60 T_a}{2\pi I_a}$

$\phi E_b = \frac{P_{mech}}{\omega} \Rightarrow \phi = \frac{1000 E_b}{\omega I_a}$

$\Rightarrow \phi = \frac{2\pi T_a}{60 I_a}$

speed vs. torque

$\Rightarrow T \propto \frac{1}{\omega}$

$\Rightarrow T \propto \frac{1}{\omega}$

2. speed vs. torque

3. speed vs. torque

4. speed vs. torque

5. speed vs. torque



Speed vs Torque

(i) Torque vs armature current for a motor


$$T \propto \phi I_a$$

$$\phi \propto I_f$$

$$I_f \propto T_a \propto I_a$$

V_t and R_a is constant. $\therefore$ ϕ is constant. $\therefore$ $T \propto I_a$


$$\therefore T \propto I_a$$



(ii) Speed vs armature current


$$N \propto \frac{E_b}{\phi}$$

ϕ is constant. $\therefore N \propto E_b$ and R_a is constant. $\therefore$ $N \propto \frac{1}{I_a}$



(iii) Speed vs Torque

$$T \propto \frac{1}{N}$$



Compound Motor

1. Torque vs. speed characteristics

Cumulative $\frac{\phi_{sc} + \phi_{sh}}{\phi_{sc}}$

Differential $\frac{\phi_{sc} - \phi_{sh}}{\phi_{sc}}$


2. Speed vs. Torque characteristics

ϕ_{sc} constant $\rightarrow$ $\frac{d\omega}{d\tau} = 0$


Now ϕ_{sh}

$(\phi_{sc} + \phi_{sh}) \rightarrow$ Cumulative

$(\phi_{sc} - \phi_{sh}) \rightarrow$ Differential



1. Torque vs. speed



$T \propto \phi I_a$

$\phi = \phi_{sc} + \phi_{sh}$

$\phi_{sc} =$ constant

$\phi_{sh} \propto I_a$

$\phi = (\phi_{sc} + \phi_{sh})$


$\phi = (\phi_{sc} + \phi_{sh})$

$\phi_{sh} \propto I_a$

Power developed in a synchronous motor is

Given is the turning and twisting moment

$T = F \times r$
 $\text{Workdone} = F \times d$
 $= P \times \text{time}$



Power developed = Workdone / time in sec

$P = \frac{F \times d}{t}$
 $P = F \times v$

$\Rightarrow T \times \omega$ (where ω is angular speed)

$\therefore P_m = T_m \times \omega$

$P_m = T_m \times \omega$

$\Rightarrow P_m \times I_a = T_m \times \omega$ (Given $P_m = 1000 \text{ W}$)

$\Rightarrow \frac{1000 \times 230}{230 \times 2} = T_m \times \frac{2\pi \times 3000}{60}$

$\Rightarrow \frac{1000 \times 230}{460} = T_m \times \frac{2\pi \times 3000}{60}$

$\Rightarrow \frac{1000 \times 230}{460} = T_m \times 2\pi \times 30$

$\Rightarrow T_m = \frac{1000 \times 230}{460 \times 2\pi \times 30}$

$\Rightarrow T_m = \frac{1000 \times 230}{460 \times 2\pi \times 30}$

$P_m \times T_m = I_a \times \omega$

$\Rightarrow P_m \times T_m = T_m \times \frac{2\pi \times 3000}{60}$

$\Rightarrow P_m = \frac{I_a \times \omega}{T_m}$

$\Rightarrow T_m = \frac{P_m \times 60}{I_a \times 2\pi \times 3000}$

Q. A 250V, 4 pole wave connected DC series motor has 752 conductors on its armature. It has a series resistance of 0.75Ω. The motor takes a current of 40 amp. Estimate the speed & torque developed by it.

25 mWb

Given
 $V_t = 250V$

$P = 4$

$A = 2$

$Z = 752$

$R_a + R_s = 0.75\Omega$

$I_a = I_s = 40A$

$\Phi = 25 \text{ mWb} = 25 \times 10^{-3} \text{ Wb}$

$T_a = \frac{0.159 \times 10^3 \times I_a}{Z}$

$= \frac{0.159 \times 4 \times 25 \times 10^{-3} \times 752 \times 40}{1}$

$= 239.136 \text{ Nm}$

$N = \frac{239.136}{T_a} = \frac{239.136}{239.136} \times 1000 \text{ rpm}$

$E_b = \frac{239.136}{40A}$


$E_b = V_t - I_a(R_a + R_s) + 2\Phi$

$= 250 - 40 \times 0.75 = 220V$

$220 = \frac{4 \times 25 \times 10^{-3} \times 352 \times N}{60 \times 2}$

$\Rightarrow \frac{220 \times 60}{4 \times 25 \times 10^{-3} \times 352} = N$

$\Rightarrow N = 951.0638 \text{ rpm}$



$\omega = 2\pi f$

$\omega = 2\pi \times 50$

$\omega = 314.159 \text{ rad/s}$

$\omega = \frac{2\pi \times 50}{60}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

$\omega = 5.236 \text{ rad/s}$

Q. A 230V DC shunt motor runs at 900 rpm. The armature current is 50 amp. Calculate speed if the torque is doubled. Given resistance is 0.2Ω.


Given Data

$$V_t = 230V$$

$$N_1 = 900 \text{ rpm}$$

$$I_{a1} = 50 \text{ amp}$$

$$R_a = 0.2 \Omega$$



$$\text{If } E_b = V_t - I_a R_a = 0$$

$$= 230 - (50 \times 0.2) = 230 - 10 = 220$$

$$E_b = 220$$

$$T_1 = \frac{9.55 \times E_b I_a}{N} = \frac{9.55 \times 220 \times 50}{900} = 210$$

$$T_2 = 2T_1 = 420$$

$$T \propto I_a$$

We know,

$T \propto I_a$ (in shunt motor)

$$\Rightarrow \frac{T_1}{T_2} = \frac{I_{a1}}{I_{a2}}$$

$$\Rightarrow \frac{T_1}{2T_1} = \frac{I_{a1}}{I_{a2}} \Rightarrow \frac{1}{2} = \frac{50}{I_{a2}}$$

$$\Rightarrow I_{a2} = 100 \text{ amp}$$

$$1) E_{b2} = V_t - (I_{a2} R_a) = 0$$

$$= 230 - (100 \times 0.2) = 230 - 20 = 210 \text{ V}$$

We know,

$$E_b \propto N \quad \left(\because E = \frac{N \phi Z}{60 A} \text{ (constant)} \right)$$

$$\Rightarrow \frac{E_{b1}}{E_{b2}} = \frac{N_1}{N_2}$$

$$\Rightarrow \frac{E_{20}}{I_{20}} = \frac{E_{30}}{I_{30}}$$

$$\Rightarrow I_{20} = \frac{500 \times 210}{210} = 474.27 \text{ or } 474.27 \text{ A}$$

Q3. A short D.C. machine has a constant resistance of 0.1Ω and field resistance of 100Ω . The machine rated terminal voltage is 250 V . Find the ratio of speed at generation and motoring. The current is 50 A in both case.


Ans. Given Data:

$$R_a = 0.1 \Omega$$

$$R_f = 100 \Omega$$

$$V_t = 250 \text{ V}$$

$$I_a = 50 \text{ A}$$



$$\frac{N_g}{N_m} = \frac{E_g}{E_m}$$

At generation:

$$E_g = \frac{V_t}{K} = \frac{250}{K} = 250 \text{ V}$$

$$I_a = I_f = I = 50 \text{ A} = 50 \text{ A}$$

$$I_a = I_f = I = 50 \text{ A} = 50 \text{ A}$$

$$V_t = 250 \text{ V}$$

$$E_g = 250 \text{ V}$$

$$E_g = V_t + I_a R_a$$

$$250 = 250 + 50 \times 0.1 = 255 \text{ V}$$

$$\frac{N_g}{N_m} = \frac{E_g}{E_m}$$


$$\Rightarrow \frac{N_g}{N_m} = \frac{255}{250} = 1.02$$

Practical - 10 - 11 - 12 - 13 - 14 - 15 - 16 - 17 - 18 - 19 - 20 - 21 - 22 - 23 - 24 - 25 - 26 - 27 - 28 - 29 - 30 - 31 - 32 - 33 - 34 - 35 - 36 - 37 - 38 - 39 - 40 - 41 - 42 - 43 - 44 - 45 - 46 - 47 - 48 - 49 - 50 - 51 - 52 - 53 - 54 - 55 - 56 - 57 - 58 - 59 - 60 - 61 - 62 - 63 - 64 - 65 - 66 - 67 - 68 - 69 - 70 - 71 - 72 - 73 - 74 - 75 - 76 - 77 - 78 - 79 - 80 - 81 - 82 - 83 - 84 - 85 - 86 - 87 - 88 - 89 - 90 - 91 - 92 - 93 - 94 - 95 - 96 - 97 - 98 - 99 - 100

Speed
~~Flux~~ Control of shunt motor by ~~flux~~ control
 method

V_t = terminal voltage

I_{a_1} = Armature current
 without external
 resistance added to
 the shunt field.



I_{a_2} = Armature current with
 external resistance added to
 the shunt field.

N_1 = Speed without external resistance is
 added to the shunt field.

N_2 = Speed with external resistance
 added to the shunt field.

Φ_1 : Flux without external resistance added to the short field.

Φ_2 : Flux with external resistance added to the short field.

$$E_b = V_t - I_a R_a$$

$$\Rightarrow \frac{E_b Z_K}{I_a + I_a R_a} = V_t - I_a R_a$$

$$\Rightarrow K_a \Phi = V_t - I_a R_a$$

$$\Rightarrow K_a \Phi = \frac{V_t - I_a R_a}{\frac{Z_K}{I_a + I_a R_a}} \quad \Rightarrow \text{for } \frac{E_b}{K_a} = 1 \text{ at}$$

$$E_b = K_a \Phi$$

$$E_{b1} = V_t - I_{a1} R_{a1}$$

$$E_{b2} = V_t - I_{a2} R_{a2}$$

$$K_a \Phi_1 = V_t - I_{a1} R_{a1}$$

$$\frac{E_{b1}}{I_{a1}} = \frac{K_a \Phi_1}{I_{a1}} = \frac{V_t - I_{a1} R_{a1}}{I_{a1}}$$

$$\Rightarrow \frac{E_{b1}}{I_{a1} \Phi_1} = \frac{V_t - I_{a1} R_{a1}}{I_{a1} \Phi_1}$$

Q1. A 250 V DC shunt motor has a mechanical resistance of 0.2 in at no load. It takes an armature current of 50 A when run at 1000 rpm. If the flux of the motor reduced by 10% without changing the load torque, find the new speed of the motor.

Problem 1: A transformer with 2500 turns on the primary and 500 turns on the secondary is connected to a 240V AC source. The primary resistance is 0.95 Ω and the secondary resistance is 0.05 Ω . The primary current is 5.0 A. Calculate the secondary current, the primary induced EMF, and the secondary induced EMF.

$$N_1 = 2500$$

$$R_1 = 0.95 \Omega$$

$$I_1 = 5.0 \text{ A}$$

$$N_2 = 500$$

$$R_2 = 0.05 \Omega$$

$$I_2 = ?$$

$$E_1 = ?$$

$$E_2 = ?$$

$$I_1 = 5.0 \text{ A}$$

$$I_1 R_1 = 0.95 \times 5.0 = 4.75 \text{ V}$$

$$I_2 R_2 = 0.05 \times I_2 = 0.05 I_2$$

$$I_2 = \frac{I_1 R_1}{R_2} = \frac{4.75}{0.05} = 95 \text{ A}$$

$$E_1 = ?$$

$$\frac{E_1}{E_2} = \frac{N_1}{N_2} = \frac{2500}{500} = 5$$

$$E_1 = 5 E_2 = 5 \times 240 = 1200 \text{ V}$$



$$E_2 = \frac{E_1}{5} = \frac{1200}{5} = 240 \text{ V}$$

$$I_1 = 5.0 \text{ A}$$

$$I_2 = 95 \text{ A}$$

$$E_1 = 1200 \text{ V}$$


$$E_2 = 240 \text{ V}$$



Q₁ A 230 V. shunt motor of 800 rpm. takes an armature current of 50 amp. If a resistance is to be added in the field circuit so, that the speed will increase to 1000 rpm at an armature current of 50 amp. Assume $R_a = 0.2 \Omega$ & $E_{b1} = 215$ and $E_{b2} = 230$ respectively.

Given Data:-

$V_s = 230 \text{ V}$
 $N_1 = 800 \text{ rpm}$
 $I_{a1} = 50 \text{ amp}$
 $E_{b1} = 215$
 $N_2 = 1000 \text{ rpm}$
 $I_{a2} = 50 \text{ amp}$
 $R_a = 0.2 \Omega$



To find:-

$$\frac{V_s - E_{b1}}{R_a} = \frac{V_s - E_{b2}}{R_a + R_f}$$

$$I_{a1} = \frac{V_s - E_{b1}}{R_a}$$

$$I_{a2} = \frac{V_s - E_{b2}}{R_a + R_f}$$

As the Φ is same,

$$\Rightarrow \Phi \propto \frac{1}{N}$$

As Φ is same,

$$\Rightarrow \Phi \propto \frac{V_s - E_b}{R_a + R_f}$$

$$N_1 \times \frac{V_1}{R_{a1}} = \frac{V_2 \times I_{a2} R_{a2}}{R_{a1} + R_{a2}} \quad \text{--- for } R_{a1} \neq R_{a2}$$

$$N_1 \times \frac{250}{R_{a1} + R_{a2}} = \frac{250 \times I_{a2} R_{a2}}{R_{a1} + R_{a2}} \quad \text{--- for } R_{a1} = R_{a2}$$

$$\Rightarrow \frac{N_1 (250 + 0)}{N_2 R_{a2}} = \frac{250 - (50 \times 0.15)}{250 - (50 \times 0.15)} \quad \text{--- (1)}$$

for $R_{a1} = R_{a2}$ condition $\Rightarrow$ $\frac{N_1 (250 + 0)}{N_2 R_{a2}} = \frac{250 - (50 \times 0.15)}{250 - (50 \times 0.15)}$

$$\Rightarrow 200 (250 + 0) = 250 \times 60.15$$

$$\Rightarrow 250 + 0 = 250 \times 0.15$$

$$\Rightarrow R_{a1} = 50 \times 0.15$$

Speed Control of Shunt motor by armature control method.

1. Armature current without added resistance



2. Armature current with added resistance

3. Back EMF without added resistance

4. Back EMF with added resistance

5. Armature current with added resistance

6. Armature resistance added to the armature circuit.

$$V = E_b + I_a R_a$$

$$V = E_b + I_a R_a$$

$$\frac{V - E_b}{R_a} = \frac{V - E_b}{R_a}$$

Φ is constant because R_m and Φ is constant

$$\frac{N_1}{N_2} = \frac{V_1 - I_{a1} R_a}{V_1 - I_{a2} (R_a + R_s)}$$

when $I_{a1} \neq I_{a2}$ the R_a is



Q: A DC shunt motor fed from 240V supply & the torque is proportional to the square of the speed and it takes 45 Amp when running at 900 rpm. What resistance must be inserted in armature circuit in order to reduce the speed to 270 rpm. If the armature resistance and shunt field resistance are 0.1 Ω and 110 Ω respectively.

Given Data:

$$V = 240 \text{ V}$$

$$T \propto N^2 \Rightarrow \frac{T_1}{T_2} = \left(\frac{N_1}{N_2} \right)^2$$

$$I_{a1} = 45 \text{ Amp}$$

$$N_1 = 900 \text{ rpm}$$

$$N_2 = 270 \text{ rpm}$$

$$R_a = 0.1 \Omega$$

$$R_{sh} = 110 \Omega$$

$$I_{sh} = \frac{V}{R_{sh}} = \frac{240}{110} = 2.18 \text{ Amp}$$

$$I_a = I_{a1} + I_{sh}$$

$$\Rightarrow I_{a1} = I_a - I_{sh} = 45 - 2.18 = 42.82 \text{ Amp}$$

$$E_{b1} = V - I_{a1} R_a$$

$$= 240 - (42.82 \times 0.1)$$



$$= 235.7 \text{ V}$$

$$E_{b2} = ?$$


$$\frac{E_{b1}}{E_{b2}} = \frac{N_1}{N_2}$$

$$\Rightarrow \frac{235.7}{E_{b2}} = \frac{900}{270}$$

$$\Rightarrow E_{b2} = \frac{235.7 \times 270}{900}$$



For a transformer, the primary and secondary windings are connected in series. The primary winding is connected to a 220V AC source. The secondary winding is connected to a load resistor. The transformer is ideal.



$$\Rightarrow \frac{V_1}{V_2} = \frac{I_2}{I_1}$$

$$\Rightarrow \frac{43}{I_2} = \frac{(900)^2}{(700)^2}$$

$$\Rightarrow I_2 = \frac{43 \times 700^2}{(900)^2} = 26.01 \text{ Ampere}$$

whereas, the primary current is 43A.

$$\frac{N_1}{N_2} = \frac{V_1}{V_2} = \frac{I_2}{I_1}$$

$$\frac{900}{700} = \frac{220}{V_2} \Rightarrow V_2 = \frac{220 \times 700}{900} = 167.78 \text{ V}$$

$$\Rightarrow \frac{P_1}{P_2} = \frac{V_1 I_1}{V_2 I_2} = 1$$

$$\Rightarrow 220 \times 43 = 167.78 \times I_2$$

$$\Rightarrow I_2 = \frac{220 \times 43}{167.78} = 52.23 \text{ A}$$

$$\Rightarrow 26.01(0.1 + R) = 220 - 167.78$$

$$\Rightarrow 26.01(0.1 + R) = 52.23$$


$$\Rightarrow 0.1 + R = \frac{52.23}{26.01} = 2.008$$

$$\Rightarrow R = 2.008 - 0.1 = 1.908 \Omega$$

$$\Rightarrow R = 1.908 \Omega$$

Therefore, the resistance of the secondary winding is 1.908 ohms.

Speed control of DC motor by varying the terminal voltage



The speed control method consists of induction motor, DC generator, DC motor.


When the motor speed is compared with the generator, the induction motor and the DC generator is called speed generator.

The speed supply is given to the field winding of the generator.

When the induction motor and the DC generator are at same speed, the DC field current supply is induced to the DC generator. The speed of the generator is given to the DC motor, the DC motor input voltage is provided by this method.

Consequently this method is used for increasing the speed.

Speed control of DC series motor by flux control
 method by resistance connected in series




$I_a = I_f$



Current I_f is limited by connecting a resistance parallel to the field winding


Speed

By parallel shunt method






It maintains a constant load torque
 as the speed of the motor increases
 due to the increase in flux. If the flux increases
 speed will decrease.

Flux control method




Here flux is controlled by the
 resistance connected in series.



Given Data:

- unexcited magnetic circuit & μ_r constant, of
- $R_s = 0$
- $N_1 = 10$
- $I_{a1}, I_{a2} = 50 \text{ Amp.}$
- $V_1 = 500 \text{ V}$
- $T \propto N^3$
- $N_2 = 0.75 \times$
- $N_3 = 7$



we know,

$T \propto \Phi I_a$

$\Rightarrow T \propto I_a I_a$ ($\because \Phi \propto I_a$ in series motor)

$\Rightarrow T \propto I_a^2$

$$\Rightarrow \frac{T_1}{T_2} = \frac{I_{a1}^2}{I_{a2}^2}$$

we have

$T \propto N^3$

$$\Rightarrow \frac{T_1}{T_2} = \frac{N_1^3}{N_2^3}$$

$$\therefore \frac{I_{a1}^2}{I_{a2}^2} = \frac{N_1^3}{N_2^3}$$

$$\Rightarrow \frac{(50)^2}{I_{a2}^2} = \frac{N^3}{(0.75N)^3}$$

$$\Rightarrow \frac{2500}{I_{a2}^2} = \frac{1}{0.421}$$

$$2500 \times 0.421 = I_{a2}^2$$

$$I_{a2} = 1054.68$$

$$I_{a2} = \sqrt{1054.68} = 32.47 \text{ Amp.}$$

$$E_{b1} + V_f = I_{a1} (R_a + R_{se})$$

R_a and R_{se} are not given, so neglected

$$\text{with } V_f = 500 \text{ V}$$

we know

$E_b \propto \Phi N$

$$\Rightarrow \frac{E_{b1}}{E_{b2}} = \frac{\Phi_1 N_1}{\Phi_2 N_2}$$

$$\Rightarrow \frac{500}{E_{b2}} = \frac{I_{a1}}{I_{a2}} \times \frac{N}{0.75N} \quad (\because \Phi \propto I_a)$$

$$\Rightarrow \frac{500}{E_{b2}} = \frac{50}{32.47} \times \frac{1}{0.75}$$

$$\Rightarrow E_{b2} = \frac{500 \times 32.47 \times 0.75}{50}$$

$$\Rightarrow E_{b2} = 243.525 \text{ V}$$

We know,

$$E_b = V - I_a R_a \text{ (at full load)}$$

$$\Rightarrow 243.512 = 500 - 22.47 \times R_a$$

$$\Rightarrow 22.47 R_a = 500 - 243.512 = 256.488$$

$$\Rightarrow R_a = \frac{256.488}{22.47}$$

$$\Rightarrow R_a = 11.41 \Omega$$

Q2. A DC shunt motor whose field is excited by a magnetic circuit and with negligible

Q2. The speed of 24.3 kV series motor working on 500 supply ~~at full load~~ is 1500 rpm at full load and the efficiency is 85%. The torque is made 50% of the full load torque. Calculate the speed of the motor. Assume the magnetic circuit is unsaturated and field resistance is 100 ohms.

Given Data:-

$$V = 24.3 \text{ kV}$$

$$V_f = 100 \text{ V}$$

$$R_f = 100 \Omega$$


$$\eta = 85\% = 0.85$$

$$T = 50\% \text{ of } T_{fl}$$

$$R_a = 10 \Omega$$

$$R_a + R_f = 110 \Omega$$

$$\eta = 85\% = 0.85$$



$$\text{Avg } \eta = \frac{P_{out}}{P_{in}}$$

$$\Rightarrow 0.9 = \frac{31.23 \times 10^3}{P_{in}}$$

$$\Rightarrow P_{in} = \frac{31.23 \times 10^3}{0.9} = 34694.44 \text{ W} = 34.694 \text{ kW}$$

$$P_{in} = V_t I_L \Rightarrow I_L = \frac{P_{in}}{V_t}$$

$$I_{L1} = \frac{34.694 \times 1000 \text{ W}}{500} = 69.388 \text{ A}$$

$$I_{L1} = I_{L2}$$

$$P_{L1} = V_t - I_{L1}(R_{L1} + R_{L2})$$

$$= 500 - 69.388 \times 0.5$$

$$= 500 - 34.694 = 465.306 \text{ V}$$

$$P_{L2} = V_{L2} - I_{L2}(R_{L1} + R_{L2})$$

$$T_{L1} = \frac{0.45 \times P_{L1}}{I_{L1}} = \frac{0.45 \times 465.306}{69.388} = 3.03 \text{ Nm}$$

we know,

$$T \propto \phi I_a$$

$$\Rightarrow T_{L1} \propto I_{a1} \quad (\phi = \text{constant})$$

$$\Rightarrow \frac{T_{L1}}{T_{L2}} = \frac{I_{a1}}{I_{a2}}$$

$$\Rightarrow \frac{3.03}{100} = \frac{I_{a1}}{100} \Rightarrow I_{a1} = 3.03 \text{ A}$$

$$\Rightarrow P_{L2} = \frac{3.03 \times 465.306}{100} = 14.10 \text{ W}$$

$$P_{L2} = V_t - I_{a2}(R_{L1} + R_{L2})$$

$$= 500 - 3.03(0.5 + 0.5)$$

$$= 500 - 3.03 = 496.97 \text{ V}$$

we know,

$$I_a \propto \phi$$

$$\Rightarrow E_{b1} \propto I_{a1} \quad (\phi = \text{constant})$$

$$\frac{E_{B1}}{P_{m1}} = \frac{N_1}{N_{B1}}$$

$$\frac{458 \times 35}{100 \times 31} = \frac{450}{N_{B1}}$$

$$N_{B1} = \frac{450 \times 100 \times 31}{458 \times 35}$$

$$N_{B1} = 210.55 \text{ rpm}$$

(Rev)

Tested of two machines

1. Brake Test

$$P_{br} = T \omega$$

$$P_{br} = T \omega$$

$$= 0.2 \times 100 \times 2\pi$$

$$= 12.56 \text{ Nm}$$

$$= 12.56 \times 1000 \times 2\pi \times 210.55$$

$$= 10.7 \text{ kW}$$

2. And by the spring balance

the reaction of the shaft of the motor

is known of value

at speed of 210.55 rpm

Procedure:-

→ Connect the belt so that the machine will have the intended height

→ Fix the machine at the motor

→ Connect the machine at the motor

light the belt

→ Input power to the motor is 10.7 kW

Output power of the motor is

$$P_{br} = T \omega$$

$$= 12.56 \times 1000 \times 2\pi \times 210.55$$

$$= (S_1 - S_2) \times 9.81 (R_1 + R_2) \times \frac{2\pi N}{60}$$

Disadvantages:-

→ Considerable amount of energy is wasted
→ It is generally performed in small machine.

→ The reading of the spring balance is not steady.

Q. A brake test on a small DC shunt motor gives the following data.

(i) Spring balance reading as kg and kg.

(ii) Diameter of the shaft is 4.5 cm.

(iii) Thickness of the belt is 0.25 cm.

(iv) Speed is 1500 rpm

(v) Applied voltage is 230 V

(vi) Line current is 12.5 A

Calculate the shaft torque and efficiency.

Given Data:-

$$S_1 = 25 \text{ kg}$$

$$S_2 = 9 \text{ kg}$$

$$d = 0.25 \text{ cm} = 0.25 \times 10^{-2} \text{ m}$$

$$D = 4.5 \text{ cm} = 4.5 \times 10^{-2} \text{ m}$$

$$t = \frac{D-d}{2} = \frac{4.5 - 0.25}{2} \times 10^{-2} \text{ m} = 2.125 \times 10^{-2} \text{ m}$$

$$N = 1500 \text{ rpm}$$

$$V = 230 \text{ V}$$

$$I_L = 12.5 \text{ A}$$

$$P_{in} = V \times I_L = 230 \times 12.5 = 2875 \text{ W}$$

$$T_{br} = (S_1 - S_2) \times 9.81 (R_1 + R_2) \times \frac{2\pi N}{60}$$

$$= (25 - 9) \times 9.81 (2.125 \times 10^{-2} + 0.25 \times 10^{-2})$$

$$\times \frac{2\pi \times 1500}{60}$$


$$P_{avg} = 10 \times 2.81 \times 10^{-3} = 28.1 \text{ mW}$$

$$P_{avg} = 1465.52 \text{ mW}$$

$$P_{eff} = \frac{P_{avg}}{P_{avg}} = \frac{1465.52}{1000} = 1.46552$$

$$= 48.75\%$$

Autotransformer



For the same maximum current

Total loss is minimum. Standard loss formula

In auto transformer, single winding can be used.

$$P_{loss} = \frac{P_{out}}{P_{in}} = \frac{P_{out}}{P_{in}} = \frac{P_{out}}{P_{in}}$$

In the autotransformer, the winding is with rated voltage. And rated speed is maintained. And the efficiency of the motor.

Advantages:-

This aut is generally used in power system. Because it is very compact and efficient. It is used in power while performing the task.

Q. A 400V DC shunt motor runs at no load with armature resistance of 0.5 ohm and shunt field resistance of 200 ohm. Calculate line current and efficiency when the motor takes a line current of 50 amp.

Given Data:-


$$V_a = 400 \text{ V}$$

$$I_{a0} = 5 \text{ amp}$$

$$R_a = 0.5 \Omega$$

$$R_{sh} = 200 \Omega$$

$$I_L = 50 \text{ amp}$$



$$I_{sh} = \frac{V_a}{R_{sh}} = \frac{400}{200} = 2 \text{ amp}$$

$$I_a = I_L - I_{sh} = 50 - 2 = 48 \text{ amp}$$

$$I_L = I_a + I_{sh} = 48 + 2 = 50 \text{ amp}$$

At no load condition:

Input power = $V_a I_L$

$$P_{in} = I_a^2 R_a + I_{sh}^2 R_{sh}$$

$$P_{in} = 48^2 \times 0.5 + 2^2 \times 200$$

$$P_{in} = 1152 + 800 = 1952 \text{ W}$$

$$P_{in} = 1.952 \text{ kW}$$

$$P_{out} = P_{in} - P_{loss}$$

$$P_{out} = 1952 - 1152 = 800 \text{ W}$$

At full load condition:

Input power = $V_a I_L$

$$P_{in} = P_{out} + I_a^2 R_a + I_{sh}^2 R_{sh}$$


$$P_{in} = 800 + 48^2 \times 0.5 + 2^2 \times 200$$

$$P_{in} = 800 + 1152 + 800 = 2752 \text{ W}$$

$$\eta = \frac{P_{out}}{P_{in}} = \frac{16.851.5}{10000} = 0.168515$$

$$\eta = \frac{P_{out}}{P_{in}} = \frac{16.851.5}{10000} = 0.168515 \times 100 = 16.8515\%$$

TRANSFORMER



A transformer is an electric device in which electrical energy is transformed from one circuit to another without the frequency and voltage.

Principle of Transformer

Consider an ideal transformer, which is given by that transformer that has no loss energy with other by in the primary winding. Now, if we assume that an AC source is connected in the primary winding. If we apply voltage in the primary winding, the flux is induced in the primary winding. This flux is linked with the secondary winding. The flux is induced in the secondary winding. The flux is induced in the secondary winding. The flux is induced in the secondary winding.

Applying Fleming's Right Hand Rule, the direction of flux is from the North to South. The direction of flux is from the North to South.

electromagnetic induction the end is induced as the two ends of the winding i.e. e_1 .

The flux linked in the primary winding through the transformer core links with the secondary winding.

According to Faraday's law of electro-magnetic induction an emf will be induced in the secondary winding.

No. of turns in the primary winding
No. of turns in the secondary winding.

But equation of Transformer is:

e_1 : Instantaneous voltage developed in the primary winding.

e_2 : Instantaneous voltage developed in the secondary winding.

$$e_1 = -N_1 \frac{d\phi}{dt}$$

$$= -N_1 \frac{d}{dt} (\phi_m \cos \omega t)$$

$$= -N_1 \phi_m \omega \sin \omega t$$

$$= \omega N_1 \phi_m \sin \omega t$$

$$= N_1 \phi_m \omega \sin \omega t = \frac{2\pi}{T} \phi_m N_1$$

$$e_{avg} = \frac{E_m}{\sqrt{2}}$$

$$\phi_m = \frac{N_1 e_{avg}}{\omega} \quad \left(\because N_1 \text{ constant, } \omega = 2\pi f \right)$$

$$N_2 \phi_m = \frac{N_2 \phi_m \omega}{\omega}$$

$$N_2 e_{avg} = \frac{N_2 \phi_m \omega}{\omega}$$

$$A = \frac{E_1}{E_2} \frac{N_1}{N_2}$$
$$\gamma = \frac{N_1}{N_2} = \frac{N_1}{N_1 + N_2}$$
$$\frac{\sqrt{2}}{\sqrt{1}} = \frac{\sqrt{2}}{1}$$

Registration Fee

Diagram of Ideal Development of

$\frac{1}{\sqrt{2}} \begin{pmatrix} 1 & i \\ 0 & 1 \end{pmatrix}$

Figure 1. Schematic diagram of the experimental setup.

Page 1 Page 2 Page 3 Page 4 Page 5 Page 6 Page 7 Page 8 Page 9 Page 10 Page 11 Page 12 Page 13 Page 14 Page 15 Page 16 Page 17 Page 18 Page 19 Page 20 Page 21 Page 22 Page 23 Page 24 Page 25 Page 26 Page 27 Page 28 Page 29 Page 30 Page 31 Page 32 Page 33 Page 34 Page 35 Page 36 Page 37 Page 38 Page 39 Page 40 Page 41 Page 42 Page 43 Page 44 Page 45 Page 46 Page 47 Page 48 Page 49 Page 50 Page 51 Page 52 Page 53 Page 54 Page 55 Page 56 Page 57 Page 58 Page 59 Page 60 Page 61 Page 62 Page 63 Page 64 Page 65 Page 66 Page 67 Page 68 Page 69 Page 70 Page 71 Page 72 Page 73 Page 74 Page 75 Page 76 Page 77 Page 78 Page 79 Page 80 Page 81 Page 82 Page 83 Page 84 Page 85 Page 86 Page 87 Page 88 Page 89 Page 90 Page 91 Page 92 Page 93 Page 94 Page 95 Page 96 Page 97 Page 98 Page 99 Page 100 Page 101 Page 102 Page 103 Page 104 Page 105 Page 106 Page 107 Page 108 Page 109 Page 110 Page 111 Page 112 Page 113 Page 114 Page 115 Page 116 Page 117 Page 118 Page 119 Page 120 Page 121 Page 122 Page 123 Page 124 Page 125 Page 126 Page 127 Page 128 Page 129 Page 130 Page 131 Page 132 Page 133 Page 134 Page 135 Page 136 Page 137 Page 138 Page 139 Page 140 Page 141 Page 142 Page 143 Page 144 Page 145 Page 146 Page 147 Page 148 Page 149 Page 150 Page 151 Page 152 Page 153 Page 154 Page 155 Page 156 Page 157 Page 158 Page 159 Page 160 Page 161 Page 162 Page 163 Page 164 Page 165 Page 166 Page 167 Page 168 Page 169 Page 170 Page 171 Page 172 Page 173 Page 174 Page 175 Page 176 Page 177 Page 178 Page 179 Page 180 Page 181 Page 182 Page 183 Page 184 Page 185 Page 186 Page 187 Page 188 Page 189 Page 190 Page 191 Page 192 Page 193 Page 194 Page 195 Page 196 Page 197 Page 198 Page 199 Page 200 Page 201 Page 202 Page 203 Page 204 Page 205 Page 206 Page 207 Page 208 Page 209 Page 210 Page 211 Page 212 Page 213 Page 214 Page 215 Page 216 Page 217 Page 218 Page 219 Page 220 Page 221 Page 222 Page 223 Page 224 Page 225 Page 226 Page 227 Page 228 Page 229 Page 230 Page 231 Page 232 Page 233 Page 234 Page 235 Page 236 Page 237 Page 238 Page 239 Page 240 Page 241 Page 242 Page 243 Page 244 Page 245 Page 246 Page 247 Page 248 Page 249 Page 250 Page 251 Page 252 Page 253 Page 254 Page 255 Page 256 Page 257 Page 258 Page 259 Page 260 Page 261 Page 262 Page 263 Page 264 Page 265 Page 266 Page 267 Page 268 Page 269 Page 270 Page 271 Page 272 Page 273 Page 274 Page 275 Page 276 Page 277 Page 278 Page 279 Page 280 Page 281 Page 282 Page 283 Page 284 Page 285 Page 286 Page 287 Page 288 Page 289 Page 290 Page 291 Page 292 Page 293 Page 294 Page 295 Page 296 Page 297 Page 298 Page 299 Page 300 Page 301 Page 302 Page 303 Page 304 Page 305 Page 306 Page 307 Page 308 Page 309 Page 310 Page 311 Page 312 Page 313 Page 314 Page 315 Page 316 Page 317 Page 318 Page 319 Page 320 Page 321 Page 322 Page 323

(Faint handwritten notes)


[illegible]

1. $\frac{1}{2}$ of the total	1. $\frac{1}{2}$ of the total
2. $\frac{1}{4}$ of the total	2. $\frac{1}{4}$ of the total
3. $\frac{1}{8}$ of the total	3. $\frac{1}{8}$ of the total
4. $\frac{1}{16}$ of the total	4. $\frac{1}{16}$ of the total
5. $\frac{1}{32}$ of the total	5. $\frac{1}{32}$ of the total
6. $\frac{1}{64}$ of the total	6. $\frac{1}{64}$ of the total
7. $\frac{1}{128}$ of the total	7. $\frac{1}{128}$ of the total
8. $\frac{1}{256}$ of the total	8. $\frac{1}{256}$ of the total
9. $\frac{1}{512}$ of the total	9. $\frac{1}{512}$ of the total
10. $\frac{1}{1024}$ of the total	10. $\frac{1}{1024}$ of the total
11. $\frac{1}{2048}$ of the total	11. $\frac{1}{2048}$ of the total
12. $\frac{1}{4096}$ of the total	12. $\frac{1}{4096}$ of the total
13. $\frac{1}{8192}$ of the total	13. $\frac{1}{8192}$ of the total
14. $\frac{1}{16384}$ of the total	14. $\frac{1}{16384}$ of the total
15. $\frac{1}{32768}$ of the total	15. $\frac{1}{32768}$ of the total
16. $\frac{1}{65536}$ of the total	16. $\frac{1}{65536}$ of the total
17. $\frac{1}{131072}$ of the total	17. $\frac{1}{131072}$ of the total
18. $\frac{1}{262144}$ of the total	18. $\frac{1}{262144}$ of the total
19. $\frac{1}{524288}$ of the total	19. $\frac{1}{524288}$ of the total
20. $\frac{1}{1048576}$ of the total	20. $\frac{1}{1048576}$ of the total
21. $\frac{1}{2097152}$ of the total	21. $\frac{1}{2097152}$ of the total
22. $\frac{1}{4194304}$ of the total	22. $\frac{1}{4194304}$ of the total
23. $\frac{1}{8388608}$ of the total	23. $\frac{1}{8388608}$ of the total
24. $\frac{1}{16777216}$ of the total	24. $\frac{1}{16777216}$ of the total
25. $\frac{1}{33554432}$ of the total	25. $\frac{1}{33554432}$ of the total
26. $\frac{1}{67108864}$ of the total	26. $\frac{1}{67108864}$ of the total
27. $\frac{1}{134217728}$ of the total	27. $\frac{1}{134217728}$ of the total
28. $\frac{1}{268435456}$ of the total	28. $\frac{1}{268435456}$ of the total
29. $\frac{1}{536870912}$ of the total	29. $\frac{1}{536870912}$ of the total
30. $\frac{1}{1073741824}$ of the total	30. $\frac{1}{1073741824}$ of the total
31. $\frac{1}{2147483648}$ of the total	31. $\frac{1}{2147483648}$ of the total
32. $\frac{1}{4294967296}$ of the total	32. $\frac{1}{4294967296}$ of the total
33. $\frac{1}{8589934592}$ of the total	33. $\frac{1}{8589934592}$ of the total
34. $\frac{1}{17179869184}$ of the total	34. $\frac{1}{17179869184}$ of the total
35. $\frac{1}{34359738368}$ of the total	35. $\frac{1}{34359738368}$ of the total
36. $\frac{1}{68719476736}$ of the total	36. $\frac{1}{68719476736}$ of the total
37. $\frac{1}{137438953472}$ of the total	37. $\frac{1}{137438953472}$ of the total
38. $\frac{1}{274877906944}$ of the total	38. $\frac{1}{274877906944}$ of the total
39. $\frac{1}{549755813888}$ of the total	39. $\frac{1}{549755813888}$ of the total
40. $\frac{1}{1099511627776}$ of the total	40. $\frac{1}{1099511627776}$ of the total
41. $\frac{1}{2199023255552}$ of the total	41. $\frac{1}{2199023255552}$ of the total
42. $\frac{1}{4398046511104}$ of the total	42. $\frac{1}{4398046511104}$ of the total
43. $\frac{1}{8796093022208}$ of the total	43. $\frac{1}{8796093022208}$ of the total
44. $\frac{1}{17592186044416}$ of the total	44. $\frac{1}{17592186044416}$ of the total
45. $\frac{1}{35184372088832}$ of the total	45. $\frac{1}{35184372088832}$ of the total
46. $\frac{1}{70368744177664}$ of the total	46. $\frac{1}{70368744177664}$ of the total
47. $\frac{1}{140737488355328}$ of the total	47. $\frac{1}{140737488355328}$ of the total
48. $\frac{1}{281474976710656}$ of the total	48. $\frac{1}{281474976710656}$ of the total
49. $\frac{1}{562949953421312}$ of the total	49. $\frac{1}{562949953421312}$ of the total
50. $\frac{1}{1125899906842624}$ of the total	50. $\frac{1}{1125899906842624}$ of the total
51. $\frac{1}{2251799813685248}$ of the total	51. $\frac{1}{2251799813685248}$ of the total
52. $\frac{1}{4503599627370496}$ of the total	52. $\frac{1}{4503599627370496}$ of the total
53. $\frac{1}{9007199254740992}$ of the total	53. $\frac{1}{9007199254740992}$ of the total
54. $\frac{1}{18014398509481984}$ of the total	54. $\frac{1}{18014398509481984}$ of the total
55. $\frac{1}{36028797018963968}$ of the total	55. $\frac{1}{36028797018963968}$ of the total
56. $\frac{1}{72057594037927936}$ of the total	56. $\frac{1}{72057594037927936}$ of the total
57. $\frac{1}{144115188075855872}$ of the total	57. $\frac{1}{144115188075855872}$ of the total
58. $\frac{1}{288230376151711744}$ of the total	58. $\frac{1}{288230376151711744}$ of the total
59. $\frac{1}{576460752303423488}$ of the total	59. $\frac{1}{57646$

(1) $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$
 (2) $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$
 (3) $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$

For ordinary reasoning, the same.

Steel Core Substrate for winding




In a simplified diagram for the core type transformer, the primary and secondary windings are shown on the opposite sides of the core but in actual construction there are always interleaved to reduce the leakage flux.

Thus, the two windings interleaving in series is to reduce the leakage flux. In the core type transformer, the primary and secondary windings are connected in series. This is a common feature for transformer. Generally, the core type transformer is used for power supply.



Phase diagram of transformer

The load



For core type transformer
 I_p is used to calculate the magnetizing current

I_p is used to calculate the magnetizing current

For core type transformer
 used to calculate

For core type transformer
 used to calculate

For core type transformer
 used to calculate

For core type transformer
 used to calculate

For core type transformer
 used to calculate

For core type transformer
 used to calculate

For core type transformer
 used to calculate

For core type transformer

Input power = 2000 W

The load condition

The power factor


$$P_1 = V_1 I_1 \cos \phi$$

$$P_2 = V_2 I_2 \cos \phi$$

1st 0.6A, 2nd 0.6A, 3rd 0.6A, 4th 0.6A, 5th 0.6A, 6th 0.6A, 7th 0.6A, 8th 0.6A, 9th 0.6A, 10th 0.6A

$$V_1 = 200V$$

$$f = 50Hz$$




$$\cos \theta = \frac{I_{10}}{I_0} = \frac{0.32}{0.6} = 0.53$$



$$\theta = \cos^{-1}(0.53) = 57.76^\circ$$

$$I_q = I_0 \sin \theta = 0.6 \sin(57.76^\circ) = 0.507 \text{ Amp}$$


Phasor diagram of Ideal transformer on load.




Phasor diagram of Rectifier transformer load (lagging power factor)




Phasor diagram of practical transformer on load
 at (Unit Power Factor) $\cos \phi = 1$



Phasor diagram of practical transformer
 on load at (Leading Power Factor)



Transformer equivalent circuit, referred to



where, R_1 and X_1 goes to primary side R_2'

Referring primary side

$$P_1 = P_2$$


$$\Rightarrow \frac{V_1^2}{X_1'} = \frac{V_2^2}{X_2}$$

$$\Rightarrow R_1' = \left(\frac{V_1}{V_2}\right)^2 R_2$$

similarly

$$\frac{V_1^2}{X_1'} = \frac{V_2^2}{X_2}$$

$$\Rightarrow X_1' = \left(\frac{V_1}{V_2}\right)^2 X_2$$



where

$$R_{eq} = R_1 + R_2'$$

$$X_{eq} = X_1 + X_2'$$

Referring to secondary side

$$P_1 = P_2$$

$$\Rightarrow \frac{V_1^2}{R_1} = \frac{V_2^2}{R_2'}$$

$$\Rightarrow R_2' = \left(\frac{V_2}{V_1}\right)^2 R_1$$

$$\frac{V_1^2}{R_1} = \frac{V_2^2}{R_2}$$


$$\Rightarrow R_1' = \left(\frac{V_2}{V_1}\right)^2 R_1$$

$$\frac{V_1^2}{R_c} = \frac{V_2^2}{R_c'}$$


$$\Rightarrow R_c' = \left(\frac{V_2}{V_1}\right)^2 R_c$$

$$\frac{V_1^2}{X_p} = \frac{V_2^2}{X_p'}$$


$$\Rightarrow X_p' = \left(\frac{V_2}{V_1}\right)^2 X_p$$




Approximate equivalent circuit



Approximate equivalent circuit referred to primary side



Approximate equivalent and referring to Sec. Side



Q. A 100kVA transformer has 400 turns on the primary and 80 turns on the secondary. The primary and secondary resistances are 0.2 Ω and 0.01 Ω respectively and corresponding leakage reactances are 0.8 Ω & 0.04 Ω respectively. The supply voltage is 2200V calculate equivalent impedance referring to the primary and referring to the secondary side.

Given Data

$$P = 100 \text{ kVA}$$

$$N_1 = 400 \text{ turns}$$

$$N_2 = 80 \text{ turns}$$

$$r_1 = 0.2 \Omega$$

$$r_2 = 0.01 \Omega$$

$$x_1 = 0.8 \Omega$$

$$x_2 = 0.04 \Omega$$

$$V_1 = 2200 \text{ V}$$

we know

$$\frac{V_1}{N_1} = \frac{V_2}{N_2}$$

$$\therefore V_2 = \frac{V_1 \times N_2}{N_1} = 2200$$

$$\therefore V_2 = 440 \text{ V}$$

$$P_1 = P_2$$


Referring to primary:

$$R_2' = \left(\frac{V_1}{V_2}\right)^2 R_2$$

$$= \left(\frac{2200}{440}\right)^2 \times 0.01 = 0.25 \Omega$$

$$X_2' = \left(\frac{V_1}{V_2}\right)^2 X_2$$

$$= \frac{2200}{440} \times 0.035 = 0.175 \Omega$$




Referring to secondary side:

$$R_1' = \left(\frac{V_2}{V_1}\right)^2 R_1$$

$$= \left(\frac{440}{2200}\right)^2 \times 0.3 = 0.012 \Omega$$

$$X_1' = \left(\frac{V_2}{V_1}\right)^2 X_1$$

$$\left(\frac{440}{2200}\right)^2 \times 0.15 = 0.014 \Omega$$



$$R_2 = 0.01 + 0.012$$

$$= 0.022 \Omega$$

$$X_2 = 0.035 + 0.014$$

$$= 0.049 \Omega$$


Voltage Regulation :-

The voltage regulation of a transformer is the arithmetic or differential (not phase difference) between the no load secondary voltage and secondary voltage on load expressed as percentage of no load voltage.

$$V.R. = \frac{E_2 - V_2}{E_2}$$


E_2 : no load secondary voltage

V_2 : Secondary voltage on load



For lagging p.f.
Power factor

$$E_2 = V_2 + I_2 (R_2 + jX_2)$$



$$OC = OM + MC = E_2$$

$$\therefore E_2 - V_2 = OM = OA$$

$$= OM = AO + ON$$

$$= AO + BL$$

$$\frac{E_2 - V_2}{E_2} = \frac{I_2 R_2 \cos \phi_2 + I_2 X_2 \sin \phi_2}{E_2}$$

$$\text{of V.R.} = \frac{I_1 \cos \phi_1 + I_2 \cos \phi_2}{E_2} \times 100$$

Q.2 Reading Q.1.

$$\text{V.R.} = \frac{I_1 \cos \phi_1 + I_2 \cos \phi_2}{E_2} \times 100$$

Q.1 A 1000/400V single phase transformer has the following data

$$R_1 = 5 \Omega$$

$$R_2 = 1.2 \Omega$$

$$X_1 = 18.5 \Omega$$

$$X_2 = 4.8 \Omega$$

Determine the voltage regulation to the T/P at the secondary voltage of full load at P.F. 0.8 lagging.

Ans Given Data-

$$R_1 = 5 \Omega$$

$$R_2 = 1.2 \Omega$$

$$X_1 = 18.5 \Omega$$

$$X_2 = 4.8 \Omega$$

$$\frac{V_1}{V_2} = \frac{2000}{400} = 5$$

∴ $\cos \phi = 0.8$ (lagging)

$$R = 1.2 \Omega$$

$$I_1 = 10 \text{ A}$$

$$\text{a) } I_1 = I_2 = 10 \text{ A}$$

$$\text{b) } \Delta V = I_2 R_2 = 10 \times 1.2$$

$$\therefore \frac{\Delta V}{V_2} = \frac{12}{400}$$

$$\therefore \frac{\Delta V}{V_2} = 3\%$$

$$R_{eq} = R_1 + R_2$$

$$R_1 = \left(\frac{V_1}{V_2} \right)^2 R_2 = \left(\frac{2000}{400} \right)^2 \times 1.2$$

$$= 15 \Omega$$

$$R_{02} = R_2 + R_{02}' = 0.2 + 0.2 = 0.4 \Omega \quad \dots (2)$$

$$X_1' = \left(\frac{V_{20}}{V_1} \right)^2 \times X_1$$

$$= \left(\frac{1100}{2000} \right)^2 \times 12 = 0.48 \Omega$$

$$X_{02}' = X_2 + X_1' = 0.48 + 0.48 = 0.96 \Omega$$

$$\cos \phi = 0.8$$

$$\phi = \cos^{-1}(0.8) = 36.86^\circ$$

$$\sin \phi = \sin(36.86) = 0.6$$

$$V.R. = \frac{I_2 R_{02} \cos \phi_2 + I_2 X_{02} \sin \phi}{E_2} \times 100$$

$$= 5.6\%$$

We know.

$$V.R. = \frac{E_2 - V_2}{E_2}$$

$$\Rightarrow 5.6\% \times E_2 = E_2 - V_2$$

$$\Rightarrow 5.6\% \times 400 = 400 - V_2$$

$$\Rightarrow V_2 = 400 - 22.40$$

or

$$E_2 - V_2 = I_2 R_{02} \cos \phi_2 + I_2 X_{02} \sin \phi$$

$$\Rightarrow 400 - V_2 = 22.5$$

$$\Rightarrow V_2 = 400 - 22.5 = 377.5 \text{ V}$$

TEST ON TRANSFORMER

1. OPEN CIRCUIT TEST:



Why is it called open circuit test?
 Components of supply voltage (resistance or induced voltage) due to primary winding.
 Measure of no-load current & power consumed.

This test is conducted to determine the iron (core) loss (losses). In this test, no load voltage is applied to LV winding and the HV winding is left open circuited.

The primary primary flux voltage is measured by voltmeter and the no load current is measured by ammeter and the loss is measured by wattmeter power is measured by wattmeter.

Since the load current is 0 to 10% of full load current so the copper loss is very minimum and negligible only power the iron loss.

$$\text{Iron loss} = P_0 = V_0 I_0 \cos \phi_0$$

no load primary fluxing = ϕ_0

Primary winding = P_0


$$\cos \phi_0 = \frac{P_0}{V_0 I_0}$$

$$I_0 = \frac{P_0}{V_0 \cos \phi_0}$$

$$\text{Wattmeter reading} = P_0$$

$$\cos \phi_0 = \frac{P_0}{V_0 I_0}$$

2. Short Circuit Test



Rated current
When rated voltage is applied to the primary, the rated current flows through the secondary.
When rated value of current flows in the secondary:
Rated current I_2

This test is conducted to determine

Full load copper loss W_{cu} , R_1 , R_2 , and X_1 , X_2 .

In this test generally the LV winding is short circuited and in HV side the voltage is gradually raised till at voltage V_{sc} full load current flows in the primary. The following are the

In this test the total loss is only copper loss due to small I/p voltage.

Voltsmeter reading V_{sc}
Ammeter reading I_1
Wattmeter reading P_{sc}

$$P = I_1^2 (R_1 + R_2) = I_1^2 R_{sc}$$

$$R_{sc} = \frac{P}{I_1^2}$$

or

Total impedance referring to primary side

$$Z_{sc} = \frac{V_{sc}}{I_1}$$

Total resistance referring to primary side

$$R_1 = \sqrt{Z_{sc}^2 - R_{sc}^2}$$

Measurement of voltage (for better accuracy)
The rated current will flow through the Pt

- Q. A 10 kVA, 200/400 V, 50 Hz single phase transformer gave the following test results
 O.C Test : 200V, 1.5A, 120W primary side
 S.C Test : 20V, 50A, 400W secondary side
 Calculate magnetizing current and the component corresponding to iron loss at normal frequency and voltage.
 (ii) the magnetizing branch impedance.
 (iii) Percentage of μR when supplying full load at 0.8 power factor leading.

Given Data

$$P = 10 \text{ kVA} = 10 \times 10^3 \text{ VA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

and Power

$$\text{O.C Test : } 200 \text{ V, } 1.5 \text{ A, } 120 \text{ W primary side}$$

$$P = 10 \text{ kVA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

$$P = 10 \text{ kVA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

$$P = 10 \text{ kVA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

$$P = 10 \text{ kVA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

$$P = 10 \text{ kVA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

$$P = 10 \text{ kVA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

$$P = 10 \text{ kVA}$$

$$V_1 = 200 \text{ V}$$

$$V_2 = 400 \text{ V}$$

we know

$$P_0 = \frac{V}{I_0 \cos \phi}$$

$$\Rightarrow \cos \phi = \frac{V}{I_0 P_0} = \frac{25000}{1.87 \times 1.25 \times 10^5} = 0.64$$

$$\phi = \cos^{-1}(0.64) = 50.5^\circ$$

$$\sin \phi = 0.767$$

$$I_r = 3 I_0 \sin \phi = 1.99 \text{ Amp}$$

$$R = \frac{V}{I_0 \cos \phi} = \frac{25000}{1.87 \times 0.64} = 1762.16 \, \Omega$$

$$X_L = \frac{V}{I_0 \sin \phi} = \frac{25000}{1.87} = 1438.61 \, \Omega$$

$$P_0 = V I_0 \cos \phi$$

$$\Delta P_0 = V I_0 \sin \phi$$

$$\Rightarrow I_w = \frac{\Delta P_0}{V} = \frac{1.75 \times 10^3}{25000} = 0.07 \text{ Amp}$$

$$I_f = \frac{\sqrt{I_r^2 + I_w^2}}{1 - \cos \phi} = \frac{\sqrt{(1.99)^2 + (0.07)^2}}{1 - 0.64} = 1.573 \text{ Amp}$$

$$R_L = \frac{V}{I_w} = \frac{25000}{0.07} = 378571 \, \Omega$$

$$X_L = \frac{V}{I_f} = \frac{25000}{1.573} = 15893.25 \, \Omega$$

$$\text{G.T. loss} = 100 \times 0.01 \times 1000 = 1000 \text{ W}$$

$$P = I_0^2 R_0$$

$$\Rightarrow 1000 = I_0^2 R_0$$

$$\Rightarrow R_0 = \frac{1000}{I_0^2} = 0.01 \, \Omega$$

$$X_{L0} = \frac{V}{I_0}$$

$$= \frac{10}{1000} = 0.01 \, \Omega$$

$$X_{L0}^2 = \sqrt{I_0^2 - P_0^2} = \sqrt{(0.01)^2 - (0.01)^2}$$

$$= 0.01 \, \Omega$$

$$\frac{V_2^2}{R_{02}} = \frac{V_1^2}{R_{01}}$$

$$\Rightarrow R_{02}' = \left(\frac{V_1}{V_2} \right)^2 R_{01}$$


$$= \left(\frac{2000}{144} \right)^2 \times 0.01 = 0.2064 \Omega$$

Similarly

$$\text{H2 } \frac{V_2^2}{R_{02}} = \frac{V_1^2}{R_{01}}$$

$$\Rightarrow R_{02}' = \left(\frac{V_1}{V_2} \right)^2 R_{01}$$

$$= \left(\frac{2000}{144} \right)^2 \times 0.048 = 0.865 \Omega$$



Losses in Transformer

Copper loss / Iron loss

$$1. \text{ Copper loss } P_{cu} = k_f I^2 R$$

$$2. \text{ Eddy current loss } = k_e f^2 B_m^2 V$$

$$\text{Copper loss } = I_1^2 R_1 + I_2^2 R_2$$

$$\text{Hence, } P_{cu} = I_1^2 R_1 + I_2^2 R_2$$

$$R_{eq} = R_1 + R_2 \quad \text{or } R_{eq} = R_1 + R_2$$

Copper loss

Efficiency (Full load) :-

$$\eta = \frac{P_o}{P_i} = \frac{kVA \cos \phi_2}{kVA \cos \phi_2 + P_1 + P_{cu}}$$

Full load efficiency of transformer

$$\eta = \frac{V_2 I_2 \cos \phi_2}{V_2 I_2 \cos \phi_2 + P_1 + I_1^2 R_{eq}}$$

Condition for maximum efficiency of transformer

$$\eta = \frac{V_2 I_2 \cos \phi_2}{V_2 I_2 \cos \phi_2 + P_1 + I_1^2 R_{eq}}$$

$$\frac{d\eta}{dI_2} = 0$$

$$\frac{V_2 \cos \phi_2}{V_2 \cos \phi_2 + P_1 + I_1^2 R_{eq}} = 0$$

$$\frac{d\eta}{dI_2} = \frac{V_2 \cos \phi_2}{V_2 \cos \phi_2 + P_1 + I_1^2 R_{eq}} = 0$$

$$\eta = \frac{V_2 I_2 \cos \phi_2}{V_2 I_2 \cos \phi_2 + P_1 + I_1^2 R_{eq}}$$

$$\frac{d}{dt} \left(\frac{1}{2} m v^2 + \frac{P_1}{T_1} + \frac{1}{2} k_B T_1 \right) = \dots$$

$$\left\{ \frac{1}{2} m v^2 + \frac{P_1}{T_1} + \frac{1}{2} k_B T_1 \right\} = \dots$$

$$\frac{1}{T_1} = \frac{1}{T_2} \left[\frac{P_1}{P_2} + \frac{1}{2} \frac{v^2}{c^2} \right]$$

Q. In a Carnot engine, the temperature is

and the work done is W . Find the efficiency of the engine and the heat rejected.

Temperature is given

Let the temperature be T_1 and T_2

Let the work done be W

Let the heat rejected be Q_2

Let the heat supplied be Q_1

Let the efficiency be η

Let the heat rejected be Q_2

Let the heat supplied be Q_1

Let the efficiency be η

Let the heat rejected be Q_2

Let the heat supplied be Q_1

Let the efficiency be η

Let the heat rejected be Q_2

Let the heat supplied be Q_1

Let the efficiency be η

Let the heat rejected be Q_2

Let the heat supplied be Q_1

Let the efficiency be η

Let the heat rejected be Q_2

Let the heat supplied be Q_1

Let the efficiency be η

Let the heat rejected be Q_2

Let the heat supplied be Q_1

Let the efficiency be η

Output KVA corresponding to Maximum efficiency

$$\eta = \frac{x \text{ KVA } \cos \phi}{x \text{ KVA } \cos \phi + P_i + P_{cu}}$$

$P_i = I_1^2 R_{e1}$ (Condition for max^m efficiency $P_i = P_{cu}$)

$\Rightarrow P_i = (x I_2)^2 R_{e2}$

$\Rightarrow P_i = x^2 I_2^2 R_{e2}$

$\Rightarrow P_i = x^2 P_{cu}$

$x = \frac{P_i}{P_{cu}} = \sqrt{\frac{P_i}{P_{cu}}}$

Output KVA corresponding to max^m efficiency
 $= x \text{ output KVA (F.L.)}$

$\eta_{max} = \frac{x \text{ output KVA}}{\dots}$

- Q. A 40KVA transformer has iron loss of 450 watt and full load Cu loss of 850 watt. if the power factor of the load is 0.8 lagging calculate (i) full load efficiency (ii) the KVA load at which maximum efficiency occurs (iii) Maximum efficiency

Given Data

$P = 40 \text{ KVA} = 40 \times 10^3 \text{ VA}$

$P_i = 450 \text{ watt}$

$P_{cu} = 850 \text{ watt}$

$\cos \phi = 0.8$

$\eta_{FL} = \frac{40 \times 10^3 \times 0.8}{(40 \times 10^3 \times 0.8) + 450 + 850} = 0.9609 = 96.09 \%$

$$\eta = \sqrt{\frac{P_i}{P_{cu}}} = \sqrt{\frac{450}{850}} = \sqrt{0.5294} = 0.727$$

$$= 72.7\%$$

At max efficiency, $P_i = P_{cu}$

$$P_{cu} = P_i = 450$$

$$\eta_{max} = \frac{450 \times 0.727}{(450 \times 10^3 \times 0.4) + 450 + 450}$$

$$= 0.9625 = 96.25\%$$

Q2. The iron loss in a certain transformer is 80 watt at 25 Hz and 200 watt at 60 Hz. the maximum flux density being same. calculate total iron loss at 100 Hz at the same maximum flux density and find the value of hysteresis loss and eddy

Concept: Losses in transformer are P_h and P_e .
 Given: $P_i = 80$ watt at 25 Hz
 $P_i = 200$ watt at 60 Hz

$$P_h = k_h B_m^{1.6} f$$

$$P_e = k_e f^2 B_m^2$$

$$P_h \propto f \Rightarrow P_h = af$$

$$P_e \propto f^2 \Rightarrow P_e = bf^2$$

$$P_i = P_h + P_e$$

$$\Rightarrow 80 = af + bf^2$$

$$\Rightarrow 80 = a \times 25 + b(25)^2$$

$$\Rightarrow 8 - 25a + 625b = 0 \text{ (Equation 1)}$$

$$204 = 0.540 + 1430I^2$$

$$\text{or } 0.540 + 3100I^2 = 204 \quad \text{--- eq (1)}$$

By solving eq (1) and eq (2) we get, $I_1 = 0.001$

$$I_2 = 0.001$$

$$V_1 = 5.71945$$

$$P_1 = 0.001 \times 5.71945 = 0.00571945 \text{ watt}$$

$$P_2 = 0.001 \times 5.71945^2 = 0.003269 \text{ watt}$$

$$\text{Total loss} = P_1 + P_2 = 0.008988 \text{ watt}$$

Q. A 25 kVA 2200/220V single phase transformer has no primary resistance. It has only secondary resistance of 0.01 ohm. Find the full load efficiency at 80% power factor lagging. (other than loss is 200 watt)

Given Data:

$$P = 25 \text{ kVA}$$

$$V_1 = 2200 \text{ V}$$

$$V_2 = 220 \text{ V}$$

$$R_{02} = 0.01 \Omega$$

$$R_{01} = 0 \Omega$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{loss}} = 200 \text{ watt}$$

$$P_{\text{out}} = I_1^2 R_1 + I_2^2 R_2$$

$$= I_2^2 R_{\text{eq}}$$

$$R_{\text{eq}} = R_2 + R_1$$

$$R_1 = 1 \Omega$$

$$\Rightarrow \frac{V_1^2}{R_1} = \frac{V_2^2}{R_2}$$

$$\Rightarrow R_1 \left(\frac{V_2}{V_1} \right)^2 = R_2$$

$$R_2 = 0.01 + 0.01 = 0.02 \Omega$$

$$P_{\text{out}} = 0.11363 \text{ W}$$

$$\text{Efficiency} = \frac{P_{\text{out}}}{P_{\text{in}}}$$

$$= \frac{0.11363}{0.11363 + 0.01} = 0.916$$

$$= 91.6\%$$

Efficiency of the system is

$$\text{Efficiency} = \frac{P_{\text{out}} \text{ in kW}}{P_{\text{in}} \text{ in kW}} = \frac{0.11363}{0.11363 + 0.01} = 0.916$$

The ratio of P_{out} to P_{in} is known as the efficiency of the system. It is known as the efficiency of the system.

Q. A 500 kVA distribution transformer has a full load efficiency of 95% at which core loss is equal to iron loss. The transformer is loaded for 12 hrs. at 1/4th of full load for 7 hrs, at 1/2 load for 5 hours and full load for 2 hrs. Calculate the all day efficiency of the T/F.

Sol:

Given the efficiency of transformer supplies max. lightly load w.r. power factor is unity.

Let Core Loss = P_w

$P_w = 500 \text{ W}$

At full load $P_w = 500 \text{ W}$

$P_w = 500 \text{ W}$

At 1/4 load $P_w = 500 \text{ W}$

At 1/2 load $P_w = 500 \text{ W}$

At full load $P_w = 500 \text{ W}$

At full load $P_w = 500 \text{ W}$

$$\eta = \frac{\text{Output}}{\text{Input}} = \frac{P_{out}}{P_{out} + P_{loss}}$$

$$0.95 = \frac{500 \times 10^3}{500 \times 10^3 + P_{loss}}$$

$$0.95 = \frac{500 \times 10^3}{500 \times 10^3 + P_{loss}}$$

$$P_{loss} = 500 \text{ W}$$

$$\Delta Q_1 = \frac{5 \times 10^3}{0.25} \times 10^{-3} = 20 \times 10^{-3}$$

$$\Delta P_1 = \frac{282.15}{2} \times 10^{-3} = 141.075 \times 10^{-3}$$

$$P_1 = 2.0 - 141.075 \times 10^{-3} = 1.858925$$

$$Q_{0.9} \text{ for } 0.9 \text{ at } 2.0 = 0.985 \times 10^{-3}$$

$$\text{Full load } Q_{0.985} \text{ for } 2.0 = 0.985 \times 10^{-3}$$

$$\frac{1}{2} \text{ full load for } 0.985 \times 2 \left(\frac{2.0}{0.985} \right) R = \frac{2.0}{0.985}$$

$$= 2.030558375$$

$$\frac{1}{2} \text{ of full load for } 0.985 \times 2 \left(\frac{2.0}{0.985} \right) R = \frac{2.0}{0.985}$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

$$= 2.030558375$$

Q. 7. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 1. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 2. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 3. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 4. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 5. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 6. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 7. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 8. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 9. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 10. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 11. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 12. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 13. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 14. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 15. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

Q. 16. A 2500 W motor is used to lift a 1000 kg mass. The motor is used for 1 hour. The efficiency of the motor is 80%.

~~Total initial cost $R_{PI} = 2.4 = 36 \times 10^3$ units~~

~~For 12 hours, op. power = $2000 \times 12 = 24000$ units~~

~~For 6 hours of power = $2000 \times 6 = 12000$ units~~

~~For 3 hours of power = $2000 \times 3 = 6000$ units~~

~~Total op. power = $24000 + 12000 + 6000 = 42000$ units~~

~~$= 12000 + 12000 + 6000 = 30000$ units~~

Super loss:

$$12 \text{ hours} = \frac{24}{2000} = \frac{1}{83.33} = 1.2\%$$

$$6 \text{ hours} = \frac{12}{2000} = \frac{1}{166.67} = 0.6\%$$

$$3 \text{ hours} = \frac{6}{2000} = \frac{1}{333.33} = 0.3\%$$

In 12 hours, cu loss = 12×10^3 units

$$12 \times 10^3 \times 1.2\% = \frac{12 \times 10^3 \times 1.2}{100} = 144 \text{ units}$$

$$6 \times 10^3 \text{ cu loss} = 6 \times 10^3 \times 0.6\% = 36 \times 10^3 \times 0.6\% = 216 \text{ units}$$

$$3 \times 10^3 \text{ cu loss} = 3 \times 10^3 \times 0.3\% = 9 \times 10^3 \times 0.3\% = 27 \text{ units}$$

$$\text{Total } P_L = 144 \times 12 + 216 \times 6 + 27 \times 3 = 2427 \text{ units}$$

$$= 2427 \text{ units}$$

$$\text{Total op. power} = (24 \times 10^3 + 12 \times 10^3 + 6 \times 10^3) \times (1 - 0.012)$$

$$= 42000 \times 0.988 = 41496 \text{ units}$$

$$\eta_{\text{all day}} = \frac{P_{\text{out}}}{P_{\text{in}}} = \frac{2.14 \text{ MW}}{(2.04 \text{ MW}) + 367.2 \text{ W} + 2500 \text{ W}} \times 100$$


$$= 91.9\% \approx 92\%$$

Parallel operation of Transformers:-

Conditions:-

1. Polarity should be correctly maintained.
2. kVA ratings ratio same.
3. Per unit impedance of both the type is same.

or $\frac{R}{Z}$ ratio should be same.



Reasons of parallel operation:-

- Parallel operation is done under three conditions:-
- When there is a sudden demand of load.
- When one transformer is not able to supply the total load.
- When there is a future expansion of load.

→ The following are the advantages of parallel operation:-

Condition for parallel operation of T's

(i) They should be properly connected with their polarity.




Fig 1





Fig 2

Fig 1 shows the series connection in secondary side. Because the total voltage in the secondary side is additive which results in short circuit.

In Fig 2 it shows the parallel connection. Because the total EMF in the secondary opposes each other. So there is no circulating current. This condition is not maintained. The transformer may damaged unless they are protected by fuses and circuit breaker.

(ii) The voltage rating and Voltage ratio of the T's should be same.



If this condition is not maintained (i.e., $Z_{p1} \neq Z_{p2}$). Even a small difference in induced secondary voltage can cause large circulating currents in the secondary loop because the impedance of T/F is very low.

This causes copper loss and when the load is connected, T/F will not share the load according to their KVA rating. In the worst case, smaller capacity winding will tend to overload as the proper share of load is not taken.

(ii) The per cent on the percentage of impedance should be equal.

If this condition is not maintained, the T/F will not share the load according to their KVA rating. It can be corrected by increasing proper amount of impedance and resistance.

of both, in series with either primary or secondary circuit of T/F.

(iv) The reactance to resistance ratio of the T/F should be same.

If this condition is not maintained, the pf of the load supplied by the T/F will not be equal.

Auto Transformer

Auto Transformer is a T/F in which a part of the winding is common to both primary and secondary.

Difference between Auto transformer and 2 winding T/F is

Auto Transformer	2 winding T/F
Power transferred by Auto T/F is both coupling and induction principle.	In a winding 4% power is transferred by induction principle only.

As you know, in a transformer, the primary and secondary windings are placed on separate magnetic cores. In an auto transformer, the primary and secondary windings are placed on the same magnetic core. This is why the auto transformer is more efficient than the ordinary transformer.

Primary side of the transformer is connected to the AC supply
 when voltage V_1 is applied to the primary
 winding a current I_1 will flow from A to C
 due to this current a flux ϕ will be
 created which is moving from A to B.

Due to this flux a voltage will be
 induced in winding B as when a pulsating
 flux comes in contact with the coil an e.m.f.
 voltage developed i.e. V_2 when a load is connected
 is applied the load current I_2 will
 flow from B to A and the load terminal
 voltage is V_2 and the induced e.m.f. is E_2

$V_1 = E_1 + I_1 R_1$ (Primary side)

$V_2 = E_2 + I_2 R_2$ (Secondary side)

$I_1 = I_2$ (Current)

$V_1 = V_2$ (Voltage)

whereas
 we have

$$V_1 = E_1 + I_1 R_1 \quad V_2 = E_2 + I_2 R_2$$

$$\frac{V_1}{E_1} = \frac{V_2}{E_2} \quad \frac{V_1}{E_1} = \frac{V_2}{E_2} = \frac{I_1}{I_2} = \frac{N_1}{N_2}$$

Thus the power is transferred from

the primary to the secondary is a
 power of

(Transformer of power
 by itself only) (Transformer of power
 by conduct only)

Calculation ratio of induced power, P_{ind}

Power of air flow, P_{air} is given by

$$P_{air} = \frac{1}{2} \rho A V_1^3$$

$$P_{ind} = \frac{1}{2} \rho A V_1^3 (1 - k)$$

$$P_{ind} = \frac{1}{2} \rho A V_1^3 (1 - k)$$

$$\frac{P_{ind}}{P_{air}} = 1 - k$$

$$P_{ind} = (1 - k) P_{air}$$

* Total power transferred by propeller

$$P_{total} = P_{ind} + P_{air}$$

$$P_{total} = (1 - k) P_{air} + P_{air}$$

$$P_{total} = P_{air} (1 - k + 1)$$

$$P_{total} = P_{air} (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$


$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

$$P_{total} = \frac{1}{2} \rho A V_1^3 (2 - k)$$

Saving of Copper in Auto-transformer



The length of copper required in a winding is proportional to sq. of turns and diameter of cross-section of the winding conductor.

The area of cross-section is proportional to the cube root of the copper used and is proportional to current and no. of turns.

→ Copper used in a winding is proportional to

→ Copper used in Auto T/F = Copper used

in the primary + secondary winding

i.e. $N_1^2 + N_2^2$

Copper used in Auto T/F = $(N_1 + N_2)^2$

Ratio = $\frac{N_1^2 + N_2^2}{(N_1 + N_2)^2}$

Ratio = $\frac{N_1^2 + N_2^2}{N_1^2 + N_2^2 + 2N_1N_2}$

Ratio = $\frac{N_1^2 + N_2^2}{N_1^2 + N_2^2 + 2N_1N_2}$

Ratio = $\frac{N_1^2 + N_2^2}{N_1^2 + N_2^2 + 2N_1N_2}$

Ratio = $\frac{N_1^2 + N_2^2}{N_1^2 + N_2^2 + 2N_1N_2}$

Ratio = $\frac{N_1^2 + N_2^2}{N_1^2 + N_2^2 + 2N_1N_2}$

Ratio = $\frac{N_1^2 + N_2^2}{N_1^2 + N_2^2 + 2N_1N_2}$

Ratio = $\frac{N_1^2 + N_2^2}{N_1^2 + N_2^2 + 2N_1N_2}$

$$= 1 - \frac{2N\mu_1}{N\mu_1 + N\mu_2} = 1 - \frac{2N\mu_1}{N(\mu_1 + \mu_2)}$$

$$= 1 - \frac{2N\mu_1}{N(\mu_1 + \mu_2)} = 1 - \frac{2\mu_1}{\mu_1 + \mu_2}$$

Compared in μ_1 & μ_2 (L.R) compared in μ_1 & μ_2 using T/F

Advantages of μ_1 & μ_2 :

→ The hole tip requires less C than a wire tip.

The ~~similarity~~ similarity between μ_1 & μ_2 .

→ The hole tip provides a higher efficiency than the wire tip of similar design.

→ The hole tip has better stability. Regulated μ_1 & μ_2 using T/F of standard design.

Advantages of hole tip:

→ There is a direct connection between the primary and secondary, therefore the tip is no longer shielded & isolated from T/F.

→ If an external circuit develops in the primary, power is used up in the wire tip. The primary winding will spend more time and the right to improve with the wire tip and equivalent circuit.

Application:

Auto T/F are used to compensate the voltage drop for Transmission and distribution lines. So, they are known as booster T/F.

→ Auto T/F are used for reducing the voltage supply to AC motor during starting period.

Q1. The primary and secondary of an Auto T/F are 230 V and 75 V respectively. Calculate the current in different parts of winding when load current is 200 Amp. also calculate the saving of copper.

Ans. Given data:

$$V_1 = 230 \text{ V}$$

$$V_2 = 75 \text{ V}$$

$$I_2 = 200 \text{ Amp.}$$

~~For~~

$$P = V_1 I_1 = V_2 I_2$$

$$\Rightarrow 230 I_1 = 200 \times 75$$

$$\therefore I_1 = \frac{200 \times 75}{230} = 65.21 \text{ Amp}$$

$$\text{Current in AB (I}_1\text{)} = 65.21$$

$$\text{Current in BC (I}_2\text{)} = 200 - 65.21 = 134.79$$

$$\text{Cu saving} = \frac{V_2}{V_1} = \frac{75}{230} = 0.32$$

$$K = \frac{V_2}{V_1} = \frac{75}{230} = 0.32$$

$$\text{Cu saving} = \text{Cu used in 2 winding T/F} - (1-K) \times \text{Cu used in 2 winding T/F}$$

$$= \text{Cu used in 2 winding T/F} (1-K)$$